

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Cor. Secs 2, 3, 10, & 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3612)

Set a fir post 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 2, 3, 10, & 11 marked T25S S2 on NE, R2W S11 on SE, S10 on SW & S3 on NW faces with 5 notches on S & 2 notches on E edges, from which
A hemlock, 6" dia., bears N.51°E., 33 lks., mkd: T25S R2W S2 BT.
A chinquapin, 4" dia., bears S.47°E., 28 lks., mkd: T25S R2W S11 BT.
A rhododendron, 6" dia., bears S.75°W., 13 lks., mkd: T25S R2W S10 BT.
A fir, 24" dia. bears N.56°W., 59 lks. mkd: T25S R2W S3 BT

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page 13345)

The cor. of secs. 2, 3, 10, & 11, determined at record distance from the remaining original bearing trees:
A hemlock, 12" dia., bears N.51½°E., 33 lks., blaze healed. (Record bearing, N.51°E.) The blaze has been chopped out showing scribe marks 2R 5W S2.
A chinquapin, 5" dia., bears S.47½°E., 28 lks., blaze rotted, partial scribe marks visible. (Record bearing, S.47°E.)
A fir, 36" dia., bears N.57°W., 61 lks., blaze healed. (Record: bears N.56°W., 59 lks.)
At the corner point
Set an iron post, 36" long, 2" dia., 28" in the ground, with brass cap mkd.

T25S	R2W
S 3	S 2
S 10	S 11
1951	

from which
A hemlock, 14" dia., bears N.64°E., 33 lks., mkd. T25S R2W S2 BT.
A hemlock, 10" dia., bears S.35½°E., 32 lks., mkd. T25S R2W S11 BT.
A hemlock, 12" dia., bears S.51½°W., 120 lks., mkd. T25S R2W S10 BT.

Fd. Ok by Nick Juliano, 12/1976 - C.S. File 58/130-1
Fd. Ok by G. Lang, 2/1992 - M114-57

continued next page

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Cor Secs 2, 3, 10, & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Mark Smalley, Roseburg Forest Products - Crew: Bill Olson & Mike Fromdahl - 4/29/2003 - C.S. File 65/45-29

Found - 1951 GLO IPBC (properly marked)
51" Fir N.57°W., 40.3 healed.
New BTs- 6" Hemlock S.60°W., 8.1 scribed "S10 BT"
8" Hemlock S.27°E., 12.3 scribed "S11 BT"
10" Hemlock S.56°E., 20.1 scribed "S11 BT"

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 8/8/2022 - C.S. File 67/55-1

Found - 2½" GLO brass cap on 1¾" I.D. Iron Pipe up 12".
53"x3' sawn Fir stump N.57W., 40.3 ft. full healed blaze. O.B.T.
8" burnt-dead hemlock S.60°w., 8.1 ft., fully healed blaze. 2003
2' tall mostly burnt away hemlock S.27°E., 12.3 ft., face burnt. 2003
13"x1 ft. shattered hemlock stump S.56°E., 20.1 ft., face burnt. 2003
New - 7" D.Fir S.45°E., 10.0 ft. scribed T25S R2W S11 BT.
9" Hemlock S.83°W. 23.1 ft scribed T25S R2W S10 CS BT
5/8"x30" iron rod with plastic cap "DOUG CO SURVEYOR" south 12.0 ft.
Note - Monument is on North slope 12' north of ridge, top 28' north of gravel road.
Area burnt 9/2020
Compass decl. 14½°E.
Lat: 43°25'02.41"N Long: 122°54'50.12"W.