

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 602100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2 only, T26-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 9 Page(s) 3580)

Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 1, 2, 35 and 36 mkd. T25S S36 on NE.; R2W S1 on SE.; T26S S2 on SW.; and S35 on NW. faces, with 1 notch on E. and 5 notches on W. faces, from which
A Fir 50" dia., bears N.55°E., 20 lks. dist. mkd. T25S R2W S36 BT.
A Fir 6" dia., bears S.15°E., 51 lks. dist. mkd. T26S R2W S1 BT.
A Fir 6" dia., bears S.50°W., 27 lks. dist. mkd. T26S R2W S2 BT.
A Fir 6" dia., bears N.55°W., 27 lks. dist. mkd. T25S R2W S35 BT.

GL0 survey by C.M. Collier, Deputy Surveyor, under Instructions dated May 12/Sept. 23, 1913 - (DCSO records Vol. 10 Page(s) 4268)

The Cor. of secs. 1 and 2, located by reference to the original Fir bearing tree, 50" dia., bearing N.55°E. 20 lks. dist.; it had been faced in the bark and fire has swept it, but some traces of the markings are to be seen and this is the only tree of such size that has stood in this vicinity for more than 30 years. Some 30 year old blazes were found also, just E. of the two streams, on line leading to this point; all other bearing trees and the original post are entirely destroyed. At the cor. point so determined, I SET a Cedar post, 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 1 and 2 only, mkd. T26S S1 on SE.; R2W S2 on SW. face, with 1 notch of E. and 5 notches on W. edge, from which
A Fir 8" dia., S.44°E. 101 lks. dist. mkd. T26S R2W S1 BT.
A Fir 6" dia., S.38°W. 217 lks. dist. mkd. T26S R2W S2 BT.

Survey by G. Robert Lecklider - For: Mrs. Carl Messing - July 6, 1959 - M 11-31

Found - 4" x 4 ft. post.
22" Fir, S.44°E., 101 lks.
New BTs- 12" Fir, N.38°E., 18.5 ft.
12" Fir, S.12°W., 33.5 ft.
10" Fir, N.04°W., 10.5 ft.

(Cont. Next Page)

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 602100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2 only, T26-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Les Roberts - For: Weyerhaeuser Co. - Oct. 1977 - M 67-61

Found - 22" down Fir, S.44°E., 67 ft.
 12" Fir, N.38°E., 18.5 ft.
 12" Fir, S.07°W., 33.5 ft.
 10" Fir, N.04°W., 10.5 ft.
Set 1" aluminum pipe, from which new BTs:
 20" Fir, S.75°E., 46.0 ft. to R.R. spike.
 16" Fir, S.89°W., 21.1 ft. to R.R. spike.
 10" Fir N.04°W., 9.9 ft. to R.R. spike.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor Under Group No. 2317, Surveyed June 2010/June 2011 - DCS0 records Vol. 57 Page(s) 22783-4

The cor. of secs. 1 & 2 only, T26S R2W perpetuated by Lecklider, in 1959, further perpetuated by Roberts, in 1977, monumented with an aluminum pipe, 1" dia., firmly set, projecting 15" above the ground, from which the remains of an original bearing tree

 A decayed fir stump, size indeterminate, bears N.55°E., 13.2 ft., with no marks visible.
and the remains of bearing trees mkd. by Lecklider
 A fir, 27" dia., bears S.3¾°W., 33.4 ft., with a healed blaze.
 A fir, 15" dia., bears N.5½°W., 10.6 ft., with a healed blaze.
and bearing tree mkd. by Roberts
 A fir, 34" dia., bears S.77½°E., 47.0 ft., with a healed blaze.
 A fir, 25" dia., bears S.87°W., 21.9 ft., with a healed blaze.

At the corner point
Set a stainless steel post, 28" long, 2½" dia., 22" in the ground, directly over the aluminum pipe, with brass cap mkd.

T25S R2W
 S 36
 S 2 | S 1
T26S R2W
2010

Deposit a magnet in a white plastic case at the base of the stainless steel post.

continued next page

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 602100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2 only, T26-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2923, surveyed July 2018/March 2020- (DCSO records Vol. 59 Pages 24052-3)

The cor. of secs. 1 and 2 only, on the N. bdy. of the Tp., reported by Skeesick in 2010-11, monumented with a stainless steel post, 2½" dia., firmly set, projecting 7" above ground, with a brass cap (properly) mkd.

from which the remains of the BTs reported by Skeesick

- A decayed fir stump, size indeterminate, bears N.55°E., 13.2 ft., alongside of which is a down, decayed fir, size indeterminate, no marks visible. (Original)
- A fir, 36" dia., bears S.77½°E., 47.0 ft., with a healed blaze.
- A fir, 30" dia., bears S.3¾°W., 33.4 ft., with a healed blaze.
- A fir, 30" dia., bears S.87°W., 21.9 ft., with a healed blaze.
- A fir, 18" dia., bears N.5½°W., 10.6 ft., with a healed blaze.