

PRIMARY CORNER DESCRIPTION 1/4 Corner for 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO records, Volume 9 Page 3709)

Set Cedar post, 3 ft. long, 3" sq. 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face, from which

A Fir 30" dia. bears N.55°E., 21 lks. dist. mkd. 1/4 S BT.

A Hemlock, 12" dia. bears S.10°W., 54 lks. dist., mkd. 1/4 S BT.

A. Boyer, Deputy Co. Surveyor - Wit: Floyd Norris; Clint Bamber - June 1939 - C.S. Files 16/29 and 35/38

Renewed from original bT, N.55°E., 21 lks. which is in good shape, orig. scribe marks are on bark.

Set 4" x 4" Fir post for corner and marked new BT:

14" Maple bears S.73°W., 40.0 ft. (on slope) marked 1/4 S8 T25S R3W CS BT.

GLO Dependent Resurvey by Norman D. Price Under Special Instructions dated April 5, 1940 (DCSO records, Volume 27 Page 11585)

Point for orig. 1/4 sec. cor., determined at record bearing and distance from the old NE bearing tree.

At point for corner, set an iron post, 3 ft. long, 1" dia. 28" in the ground for 1/4 sec. cor., with brass cap mkd. 1/4

S8|S9
1944

from which

A Fir 30" dia. bears N.55°E., 21 lks. dist., with partial scribe marks visible in portion of old blaze which has been previously uncovered. The county surveyor re-blazed and re-marked this old bearing tree 1/4 S9 T25S R3W CS BT.

A Maple 12" dia. bears S.74 1/2°W., 50 lks. dist. mkd. 1/4 S8 T25S R3W CS BT. (A Co., Surveyors BT)

Doug. Co. Surveyors Office - Vernon Tracy; Jack Heritage August 1966 - C.S. File 54/27-38

Found - GLO brass cap 1944, with steel fence post alongside. (Cont. Next Page)

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Orig. 30" now 36" Fir N.55°E., 13.9 ft. shows bark scribe as recorded.
12" now 19" Maple S.74¼°W., 33.0 ft. shows healed blaze. We do not open.
New BTs - 11" R.Cedar S.33°W., 36.6 ft. mkd. ¼ S8 CS BT.
8" W.Fir N.18°E., 39.8 ft. mkd. ¼ S9 CS BT.
This corner lies on steep NW slope with blazed lines N-S-E.

Found and used, BLM Dependent Resurvey by Rogers, et al, Group #1386 1987-88 (DCSO records, Volume 48 Pages 18485-86)

Found OK by D. Edwards, Jan. 2001 - M136-33

2