

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 33

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

<p>Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3691)</p> <p>-----</p> <p>Set Oak post, 3 ft. long, 3" sq., 24" on W. face, from which A Fir 24" dia., bears S.25°E., 27 lks., mkd. ¼ S BT. A Maple 6" dia., bears N.60°W., 10 lks., mkd. ¼ S BT.</p>
<p>GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Pages 11563-64)</p> <p>-----</p> <p>Point for original ¼ sec. cor., determined by reference to the record measurements from both old bearing trees. AT point for corner, set an iron post, 3 ft. long, 1" dia., 28" in the ground, for ¼ sec. cor., with brass cap mkd.</p> <p style="text-align: center;">¼ S33 S34 1943 from which</p> <p>A Fir 32" dia., bears S.23°E., 27 lks., on which I uncovered the scribe marks BT. (Old BT) A Vinemaple 5" dia., bears N.60°W., 10 lks., with the scribe marks ¼ S BT in reverse visible on the overgrowth of the old blaze when one looks at the decayed NW side of this old BT. An Incense Cedar 14" dia., bears N.87½°E., 42 lks. mkd. ¼ S 34 BT. (New BT) A Fir 20" dia., bears S.86¼°W., 37 lks., mkd. ¼ S33 BT. (New BT)</p>
<p>Glen McChesney, for: Weyerhaeuser Co. - October 31, 1978 (Filed 12/1980) - C.S. 58/8-44 (see also 1959 C.S. 53/113-1)</p> <p>-----</p> <p>Found - Orig. 32" Fir now a 34" tipped over stump, part of chopped face remains. 1959 found bearing S.24°E., 17.8 ft. Orig. 5" Vine maple now clump, but no scribe marks remain. Record N.60°W., 6.6 ft. 1943 GLO brass cap in original position. 14" now 20" Incense Cedar bears N.86°E., 27.7 ft. scribing partly overgrown. 20" now 24" Fir stump, moved of position by logging, now S.61°W., 22.2 ft (Rec S.86¼°W., 37 lks.) Scribed face removed with butt log. "W" nails and plates referenced in 1959.</p> <p>New BT - 48" Fir N.47°E., 76.4 ft</p>
<p>continued next page</p>

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent resurvey by A. Bert Skeesick & Kenneth W. Saveland, Cadastral Surveyors and Robert H. Browning, Survey Tech, under Group No. 2212 surveyed July/Oct. 2008 - (DCSO records Vol. 57 Page(s) 22435-6)

The ¼ sec. cor. of secs. 33 and 34, perpetuated by Williams, in 1978, monumented with an iron post, 1" dia., firmly set, projecting 7" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees

A roothole bears S.23°E., 17.8 ft., alongside of which is an uprooted, sawed fir stump, 36" dia., with axe marks visible.

A vine maple cluster bears N.60°W., 6.6 ft., with no marks visible.

and the remains of bearing trees mkd. by Price

A cedar, 33" dia., bears N.87½°E., 27.7 ft., with axe marks visible.

A roothole bears S.86¼°W., 24.4 ft., alongside of which is an uprooted, sawed, decayed fir stump, with no marks visible.

and the remains of a bearing tree by Williams

A sawed fir stump, 41" dia., bears N.49°E., 80.1 ft., with no marks visible.

and a new bearing tree

A fir, 14" dia., bears N.68¾°W., 23.1 ft., mkd. ¼ S33 BT. Corner is located on a broken S. slope.