

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec Cor for 13 & 24 only (East)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Pages 3587-88)

Set Yew post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 13, 18, 19 & 24 marked T 25 S S 18 on NE.; R2W S19 on SE., R3W S24 on SW., S13 on NW. faces with 3 notches on N and S edges, from which

- A Fir 18" dia., bears N.40°E., 18 lks. dist., marked T25S R2W S18 BT.
- A Fir 24" dia., bears S.55°E., 27 lks. dist., marked T25S R2W S19 BT.
- A Fir 30" dia., bears S.21°W., 24 lks. dist., marked T25S R3W S24 BT.
- A Fir 18" dia., bears N.38°W., 129 lks. dist., marked T25S R3W S13 BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April 5, 1940 (DCSO records, Volume 27 Pages 11514-15)

Point for original sec. cor. which now refers to secs. 13 and 24 only, determined by reference to the record measurements from the old SE., SW., and NW. bearing trees.

At point for corner, Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor. of secs. 13 and 24, with brass cap mkd.

T25S | T25S
S13 | R2W

S24 | S18
R3W

1943

from which

- A Fir, 32" dia., bears S.57½°E., 27 lks. dist., mkd. T25S R2W S19 BT. I obliterate the marks on this old BT.
- A Fir 44" dia., bears S.17½°W., 24 lks. dist., with partial scribe marks on old bark blaze. I reblaze and remark this old bearing tree T25S R3W S24 BT.
- A Fir stub 20" dia., bears N.42½°W., 129 lks. dist., on which the marks B T and other partial scribe marks are visible. (Old BT)
- A Hemlock, 9" dia., bears N.38½°W., 19 lks. dist., mkd. T25S R3W S13 BT. (New BT)

Found OK, Dec. 1976, Nick Juliano, C.S. 58/130

Douglas Co. Surveyors Office - Greg Quibell; Terry Plouff; Teresa Buley - Oct. 13, 1981 - C.S. 61/29-10

Found - 1943 GL0 brass cap, properly mkd. firmly set.
Continued next page

PRIMARY CORNER DESCRIPTION Sec Cor for 13 & 24 only (East)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Orig. 24" now 38" Fir, alive with large pitched over scar, bears S.55°E., 17.8 ft.
Orig. 30" now 47" Fir stump (7 ft. high) with well healed scar, bears S.21°W., 17.2 ft. (Rec. 15.8 ft., fits to face fairly good)
Orig. 18" now 16" rotted Fir snag (10 ft. tall) bears N.38°W., 84.6 ft. (Rec. 85.1 ft.) scribed "T25S R3W S13 BT" visible on East side of tree.
9 now 12" Hemlock per 1943 resurvey, down with well healed scar bears N.38½°W., 12.5 ft. to roothole
New BTs- 13" Hemlock bears S.1°E., 36.8 ft. scribed "T25S R2W S18 CS BT" in double blaze.
10" Hemlock bears N.87°W., 18.0 ft. scribed "T25S R3W S13 CS BT" in double blaze.
9" Hemlock bears N.45°W., 62.0 ft. scribed "T25S R3W S13 CS BT" in double blaze.
Corner lies in cut line west of rock road approx. 50 ft.

Douglas Co. Surveyors Office - Randall Smith & Stephen Flause
March 30, 1995 - C.S. 64/58-8

Found - 2½" dia. Glo Brass cap on a 2" O.D. I.P. protrudes 7" above ground.
24" now 34" dia. 6' high tipped out D.Fir stump with a fully healed single blaze, estimated root wade, bears S.57½°E., 17.8' (agrees w/ rec.) OBT.
30" now 46" dia. 5' high D.Fir stump with a fully healed single blaze, bears S.17½°W., 17.5' (rec. S.17½°W., 15.8' dist could be a face measurement) OBT (stump is solid in good shape).
No other OBT's or 1943 ren BT are found.
13" now 14" dia. 6' high Hemlock stub with scribing visible on an unhealed open blaze "T25S R2W S18 CS" bears S.1°E., 36.8' (agrees with rec.) 1981 DCS0.
10" now 12" dia. 2' high Hemlock stub with scribing visible on an unhealed open blaze "S BT", bears N.87°W., 18' (agrees with rec) 1981 DCS0.
1981 DCS0 Hemlock BT bearing N.45°W., 62' is now gone.
New - 5" dia. Hemlock, double blazed and scribed "X BT" bears S.0½°W., 66.7'.
4" dia. D.Fir, double blazed and scribed "X BT", bears N.36½°W., 24.5'.
3" dia. D.Fir, double blazed and scribed "X BT", bears S.68°W., 22.1'.
_____cont.

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24 only (East)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 6/21/2023 - C.S. File 67/56-38

- Found - 2½" 1943 GL0 brass cap (properly mkd) on 2" O.D. iron pipe up 9"
28"x6 ft tipped out and burnt D.Fir stump S.57½°E., 17.8 ft. open blaze, no scribe visible.
36"x5 ft. D.Fir stump S.21½°W., 17.6 ft. rec. S.17½°W., 17.5 ft. healed single blaze add 3½" mag nail right side center.
15" D.Fir burned, dead N.36½°W., 24.4 ft. (rec. 24.5 ft.) add 3½" mag nail right side center scar not visible.
14" D.Fir burned & dead S.68°W., 22.3 ft. (rec. 22.1 ft) add 3½" mag nail right side center scar not visible.

Note - Corner on shallow SE'ly slope 265 ft north of and halfway between two Northerly running logging spur Rds.

Area burnt 9/2020
Compass decl. 14½°E.

Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 202752.681 E 255486.352