

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 049060

PRIMARY CORNER DESCRIPTION S.E. Cor. Sutherlin DLC #49

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

15" now badly rotted Cedar stump, no blazes or scribing visible, bears N.74½°W., 37.0 ft. (agrees with rec.) 1930
NE BT from 1930 is gone.
NW BT from 1965 is gone.
6" now 20" dia., D.Fir with a fully healed double blaze, bears N.40°W., 35.8 ft. (agrees w/rec.) 1965
New BTs- 36" dia., alive 30 ft high I.Cedar snag double blazed and scribed "SE DLC 49 CS BT", bears N.72°W 38.8 ft.
7" dia., D.Fir, double blazed and scribed "SE DLC 49 CS BT", bears N.4½°W, 93.4 ft.
18" dia., D.Fir, double blazed and scribed "SE DLC 49 CS BT" bears N.55½°W., 76.7 ft.

Found OK by N. Hibbs, Oct. 2002 - M141-15
FD. Ok by J. Peterson - 7/2003 (recorded 2/3/2006) M149-43