

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Sec Cor for 5 & 6; 31 & 32 T24-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Gordon & Gardner, Contract #52 dated Feb. 1855  
(DCSO records, Volume 7 Page 3026)

-----  
Sec. Post cor. of secs. 5, 6, 31 and 32.  
Drove charred stake raised mound with trench as per  
instructions.

F.C. Frear, Dep. Co. Surveyor - Wit. Alva Manning; Harrison  
Manning - Feb. 1917 - F.B. 43 Page 52

-----  
Renew cor. by proportional dist. Set in a 10" x 10" x 16"  
sandstone, buried. Witnessed by mound.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy -  
Vernon Tracy; M. Stone - May 1963 (added 10/20/2020)- C.S.  
File 53/9-119

-----  
Reported as not found  
Rock set by Frear was ploughed out.  
Replaced in approx location by man who plowed it out.  
No BTs

W.S. Barnes, For: Richard McGarvey - July 1976 - M 60-70

-----  
Set - 3/4" iron pipe by single proportion.  
Found stone with X 10.0 ft. East of 1947 (?) record.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -  
Stephen J. Flause - 1-9-2002 - C.S. File 66/32-3

-----  
1976 Prop. position.  
Found - 3/4 I.D. iron pipe flush with ground at fence corner  
FC line run North & East. (1976 M60-70)  
1917 18"x7"x4" stone with chiseled "+" is found  
loose on top of ground has no position, bears  
S.63°E., 11.5 ft. from IP  
New - 1" I.D. iron pipe with 2" dia., collar protrudes 11"  
out of ground bears S.65°E., 54.9 ft.  
SW corner of steel power line tower (PPL<sup>4</sup><sub>7</sub>BPA)  
where leg meets 3 ft. dia., concrete post bears  
N.60°E., 118.7 ft.  
East wood power pole (PPL<sup>7</sup><sub>43</sub>CO) with a 1998 inspection  
bears N.17°W., 167.7 ft.  
Corner lies 25 ft. west of power line road center  
line and gate.  
Compass decl. 17½°E.