

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 500320

PRIMARY CORNER DESCRIPTION So. 1/16 Cor. Secs. 22 and 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - BLM Dependent Resurvey - Zirpel, Corbin and Roseberry - Special Instructions dated July 8, 1957 and July 15, 1958 - (DCSO records, Volume 29 Page 12284)

-----  
Set an iron post 28" long 2½" dia. 26" in the ground, with brass cap marked:

S 1/16  
S 22|S 23

1957 from which

A Cedar 14" dia. bears N.6½°E., 59½ lks. dist. marked S 1/16 S23 BT.

A Fir 15" dia. bears N.42½°W., 104 lks. dist. marked S 1/16 S22 BT.

Doug. Co. Surveyors Office - Vernon Tracy; Mike Darby; Jack Barnett - January 1965 - C.S. File 53/47-1

-----  
Found - BLM brass cap mkd. 1957 and BTs as follows:  
14" now 18" Cedar stump N.6½°E., 39.3 ft., shows "S 1/16 S23 BT" scribe. Stump is 42" high.  
15" now 16" Fir N.42½°W., 68.6 ft. face pitched over "S 1/16 S2" visible.

New BT - 10" Cedar S.81°E., 31.1 ft. mkd: S 1/16 S23 CS BT. Corner falls in E-W fence line.

Bureau of Land Management Dependent Resurvey - Bishop and Rogers - Group #1161 - Survey, July/Sept 1983 (DCSO records Volume 46 Page 17768)

-----  
Found - 1957 BLM brass cap.  
Cedar stump, 12" dia. bears N.6½°E., 59½ lks. dist. with scribe marks S 1/16 S23 BT visible on partially healed blaze.  
Fir, 18" dia. bears N.42½°W., 104 lks. dist. with fragmentary scribe marks visible on partially healed blaze.

and a new Bearing tree:

A Cedar 10" dia. bears N.81½°E., 23½ lks. dist. mkd. S 1/16 S23 BT.

The corner is located at a fence corner, fence lines extending E. and S.

Fd. OK by K. Hoffine, Feb. 2000 - M134-31