

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 700440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 13; & 18 of T25-3

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Original - W. H. Byars, Contract #152 dated June 1871  
(DCSO records, Volume 9 Page 3665)

-----  
Set 1/4 sec. post, from which  
    A Maple 8" dia. bears S.50°E., 27 lks. dist.  
    A Fir 24" dia. bears S.50°W., 16 lks. dist.

-----  
Bureau of Land Management Dependent Resurvey - Norman Price -  
Under Special Instructions dated April, 1940 - Survey, 1943  
(DCSO records, Volume 27, Page 11525)

-----  
Point for orig. 1/4 sec. cor., determined by reference to record  
measurements from both old bearing trees.

At corner point, set an iron post, 3 ft. long, 1" dia. 28" in  
the ground, with brass cap marked: 1/4

S13|S18

1944 from which

A Maple 16" dia. bears S.67 1/2°E., 27 lks. dist. with old  
blaze healed. (Old BT)

A Fir 26" dia. bears S.64°W., 16 lks. dist. with old  
blaze healed. (Old BT)

A Red Cedar 18" dia. bears N.51°E., 95 lks. dist. mkd.  
1/4 S 18 B T. (New BT)

-----  
Found OK, BLM Resurvey, 1958 - Corbin, Zirpel & Roseberry  
(DCSO records, Volume 29 Page 12263)

-----  
Found OK by K. DeGroot, May 2004 - M146-4