

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 037030

PRIMARY CORNER DESCRIPTION SW Cor. Holman DLC #37

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - James Byron - June 1958 - C.S.  
File 49/96

-----  
Found 2" I.P. at fence cor. said to be SW Cor. DLC 37.

NOTE: There is no mention of any monument set, nor do they  
say that they accept this as the corner. The corner  
renewal visual book shows this corner as being looked for  
not found. 8/19/96 DCSO, JC.

Reported as not found DCSO May 1964 (added 6/28/2022) - C.S.  
File 49/124-89