

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 037040

PRIMARY CORNER DESCRIPTION S.E. Cor. Holman DLC #37

Alias 039030 Description S.W. Cor. Smith DLC #39
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

| |
|--|
| <p>Original - Addison R. Flint, Contract #28 dated April, 1853 ----- Set stone post (at SE cor. Cl. 37 & SW cor Cl. 39) 17x8x4. Raised mound with trench as per instructions.</p> |
| <p>L.G. Hicks, For J.F. Luse, S.L.& W. Co. Plat H, Blocks 1 & 2 Subd. Plat Volume 3 Page 7 - March, 1910 ----- 2" Galv. Pipe.</p> |
| <p>J. Byron; M. Godfrey; S. Bilow - For: C. Wahl - June 4, 1958 C.S. File 49/96 and M 10-36 ----- Found - 2" I.P. at corner under E. W. fence, 12" under surface, checks 180 ft. West to Creek. New BTs - 9" Ash bears S.39½°W., 10.2 ft. scribed S.E. DLC 37 CS BT. 12" Ash bears N.78°E., 14.0 ft. scribed S W DLC 39 CS BT.</p> |
| <p>Don Garrett, For B. Taylor - Sept. 24, 1965 - M 22-70 ----- Corner destroyed. Set - 5/8" Iron rod at corner, from which 13" Ash bears S.53°W., 151.7 ft. scribed DLC #37 BT.</p> |
| <p>Carl Sweeden - For: Blair Wilbur - Nov. 2002 - M141-19 ----- Found - 5/8" iron rod in good. No BT fd. per M22-70 New - 5/8"x30" iron rod w/red plastic cap N.23°E. 23.65' 5/8"x30" iron rod w/red plastic cap N.49°E. 21.50' 5/8"x30" iron rod w/red plastic cap S.49°E. 22.38' 5/8"x30" iron rod w/red plastic cap S.45°W. 24.73' Wood post at East end of R/W fence S.52°W., 25.30' No other Bearing Object suitable in the area.</p> |
| <p>Fd. IR 2/2019 by D. Edwards M175-25</p> |
| <p>1</p> |