

PRIMARY CORNER DESCRIPTION SE Cor. Thomas Sutherlin DLC

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Addison Flint, Contract #28 dated April, 1854.
(DCSO DLC records Page(s)188)

Set post, from which
 A B.Oak 30" dia., bears South 6 lks.
 A B.Oak 20" dia., bears N.75°E., 145 lks.

Sidney Strong - For: Sutherlin Land & Water Co. (Plat N) -
April 1911 - Vol. 3 Pg. 35

Stone monument

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - July 28, 1997 - C.S. 64/71-24

Mon. fd.- a stone protrudes 15" above ground, with a 4" by 10"
top marked on west face "C 40 T25S R5W" stone
leans 6" westerly of plumb. source unknown.
Bt's Fd.- 30" B.Oak, now remains of old oak found knocked over
and scattered around area of corner shows
evidence of being previously opened no scribing
found record south 6 lks. OBT
 20" now 39" dia. 20' high B.Oak snag, with a
previously opened healed blaze, bears N.75°E.,
95.7' (agrees with rec.) OBT
 3/4" I.D. iron pipe 2" below ground bears south
13.9' (agrees with rec.) vol. 3 pg. 35.
Mon. Set- Position of corner falls under fence set a 5/8" by
30" long iron rod with a DCSO Alum. cap
stamped "1997" is set at plumb position of
stone, protrudes 14" above ground. Stone is a
long west edge of I.R.

New Accessories -
 14" D.Fir, double blazed and scribed "SE DLC 40 CS
BT", bears N.31½°E., 25.4'.
 18" D.Fir, double blazed and scribed "SE DLC 40 CS
BT", bears S.61°W., 19.9'.
 7" D.Fir, double blazed and scribed "SE DLC 40 CS
BT", bears N.13°W., 22.2'.