

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 055040

PRIMARY CORNER DESCRIPTION S.E. Cor. Williamson DLC #55

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Contract #28 dated April, 1854

To S.E. Cor. C 55, from which
 A B.Oak 18" dia. bears S.20°E., 105 lks. dist.
 Raised mound with trench as per instructions.

F.C. Frear, Deputy Co. Surveyor - Wit. R.L. Stearns, Bob Davis
Feb. March 1919 - R.M. 1-4, C.S. File 2/17 and F.B. 46 Pg. 14
For: Stearns Estates

Renew from old BT. Set a 1" x 30" Iron pipe, from which
 An 8" W.Oak bears N.37°W., 10¾ lks.
 A 12" B.Oak bears S.66¼°E., 20½ lks.
(See also corner reported by Heydon for L.W. Estes, 1896,
Volume 2 Page 59)

Searched for not found, April 1964 - C.S. File 49/124-82

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - June 19, 97 - C.S. 64/75-27

We Opened a 21" dia. W.Oak at a fence corner, center rotted
out.