

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853
(DCSO records Vol. 9 Page(s) 3800)

Set - ¼ Sec. post, from which
A Y.Oak, 14" dia., bears N.45°W., 27 lks.
A Y.Oak, 8" dia., bears S.8°W., 17 lks.

F.C. Frear, Deputy Surveyor - Wit. R.L. Stearns, Bob Davis
Mar. 1919 - R.M. 1-4, C.S. 2/17, F.B. 46 Pg. 26 For:
Stearns Estates

Renew from old BTs. Set in a 1¼" x 40" Iron pipe from which:
A 24" B.Oak bears N.45°W., 27 lks.
A 20" B.Oak bears N.13½°E., 20½ lks.

James W. Byron, Deputy - Milo E. Godfrey; Clete Putnam
April 20, 1960 - C.S. File 49/124-48

Found - 1¼" Iron pipe at corner & NW BT as recorded, now
30" B.Oak stump. I open & find good scribing "B"
No trace of SW BT found.
Corner is under N.S. fence
New BTs - 20" B.Oak bears N.36°W., 49.4 ft. scribed ¼ S7 CSBT
11" R.Fir bears S.26°E., 46.7 ft. scribed ¼ S18
CSBT

Found Ok, Robert Dolan - July 1993, M117-41

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - May 29, 1997 - C.S. 64/75-3

Found - 1¼" O.D. iron pipe rusted into two pieces portion
on top of ground measures 14" long. (1919).
24" now rotted nearly to ground oak, with scribing
visible "BT", bears N.45°W., 17.8' (agrees
with rec.) OBT.
11" now 23" dia. D.Fir, with a fully healed double
blaze, bears S.26°E., 46.7' (agrees with
rec.) 1960.
20" now 26" dia. 1½' Oak stump, with a healed
blaze, bears N.36°W. 49.4' (agrees w/rec) 1960
Set- Portion of found iron in ground measures 24" long,
a 2 3/8" dia. brass cap on a 1 3/8" O.D. by
32" long iron pipe is set at position of found
iron pipe. Protrudes 6" above ground. Pieces
of found iron pipe are set along north edge of
BC/IP flush with ground.

Continued next page

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

DOUGLAS COUNTY SURVEYORS
T 25 S
R 5 W
 $\frac{1}{4}$ S 7
S 18
1997
OFFICE

New - 11" dia. D.Fir, doubled blazed and scribed " $\frac{1}{4}$ S7 CS BT", bears N.55°E., 24.1'.
24" dia. Madrone, double blazed and scribed " $\frac{1}{4}$ S7 CS BT", bears N.79°W., 22.9'.
12" dia. D.Fir, double blazed and scribed " $\frac{1}{4}$ S18 CS BT", bears S.71°E., 16.3'.

Found OK by C. Sweeden, July 2000 - 2000-0077
Fd. by ODOT 1/7/2009 - C.S. File 65/66-3A