

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
(DCSO records, Volume 9 Page 3792)

-----  
Set ¼ Sec. post, from which  
    A Y.Oak 13" dia. bears S.66°W., 19 lks. dist.  
    A Y.Oak 9" dia. bears N.56°W., 16 lks. dist.

BLM Dependent Resurvey, Patrick J. Reynolds under Group #476  
Survey July 25-August 30, 1962 (DCSO records Volume 31, Page  
13150)

-----  
There is no remaining evidence of the original corner.  
Set an I.P. 30" long 2½" dia. 16" in the ground, to solid rock  
& in a mound of stone, 4 ft. base, to top, with brass cap mkd.

T 25 S R 5 W

¼ S 9  
    S 16

1962

from which:

A Fir 13" dia. bears N.4°E., 41 lks. dist. mkd. ¼ S9 BT.

A Cedar 20" dia. bears S.37°E., 171 lks. dist. marked  
¼ S16 BT.

"Missing" per BLM, Oct. 9, 1981.

Fd. BC per David Edwards 2/2007 - M152-37