

PRIMARY CORNER DESCRIPTION Center ¼ Corner for Sec. 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM Subdivision of Section 35, C. Albert White; Donald R. Beck, Group #502, Survey May 3-24, 1963 (DCSO records Volume 32 Page 13367)

Point for the center ¼ sec. cor. of sec. 35, at intersection with the E. and W. center line.

Set an I.P. 28" long 2½" dia. 22" in the ground, with brass cap marked:

C ¼ S 35

1963

from which:

A Fir 14" dia. bears S.71°E., 98 lks. mkd. C ¼ S35 BT.

A Fir 20" dia. bears N.74°W., 41 lks. mkd. C ¼ S35 BT.

The corner is located in the N. and S. fence line.

BLM rehabilitation of certain corners, Timothy J. Moore, Cadastral Surveyor & Robert H. Browning, Surveying Tech., under Group #2000, 2100, & 2300, Surveyed June 2004, - (DCSO records Vol. 55 Page(s) 21498) See 2008 Plat

The center ¼ sec. cor. of sec. 35, monumented with an iron post, 2½" dia., firmly set, projecting 4" above the ground, with brass cap mkd. as reported by White & Beck in 1963

C ¼ S35

2006

from which the remains of bearing trees mkd. by White & Beck

A decayed fir stump, size indeterminate, bears S.70°E., 62.6 ft with a healed blaze. (Rec. S.71°E. 64.17 ft)

A decayed fir stump, size indeterminate, bears N.74°W., 27.1 ft. with a healed blaze.

and new BTs

A fir, 11" dia., bears S.12¾°W., 37.4 lks. mkd: C¼ S35 BT

A fir, 15" dia., bears N.65°W., 77.6 lks., mkd: C¼ S35 BT

All new bearing tree have a 2½"x ¼" nail driven at the base right side-center.

Corner is located 0.8 ft. W of a woven wire fence, with fences extending north & south.