

PRIMARY CORNER DESCRIPTION Sec. cor. for 24 & 25; 19 & 30, T25-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, James Freeman, contract #1 dated May 1851
(DCSO records, Volume 9 Page 3730)

Set post cor. to secs. 19, 24, 25, & 30 from which
A Fir 40" dia. bears S.19°W., 27 lks dist.
A Fir 16" dia. bears N.2½°W., 31 lks. dist.
A Fir 18" dia. bears N.23½°E., 35 lks. dist.
A Fir 20" dia. bears S.39°E., 120 lks. dist.

BLM Dependent Resurvey, Irving Zirpel; Lynn Roseberry; Harold Corbin; Special Instructions dated July 8, 1957-July 15, 1957
(DCSO records, Volume 29 Page 12264)

Found - Remaining orig. BT, A fir snag 55" dia. bears S.39°E., 120 lks. dist. with scribe marks 25T S visible on partially opened blaze.
Orig. Fir 70" dia. bears S.19°W., 27 lks. with a healed blaze.

At the corner point: Set an I.P. 28" long 2½" dia. 26" in the ground, with brass cap mkd:

T25S
R5W|R4W
S 24|S 19
S 25|S 30
1957

from which:
A Fir 15" dia. bears N.16½°E., 205½ lks. dist. marked T25S R4W S19 BT.
A Cedar 9" dia. bear S.75°E., 201 lks. dist. marked T25S R4W S30 BT.
A Fir 45" dia. bears N.33¼°W., 56 lks. dist. marked T25S R5W S24 BT.

Found OK by K. Hoffine, Sept. 1996 - M 126-5

Douglas County Surveyors Office - Randall Smith & Stephen Flause - 7/8/97 - C.S. 64/75-18

Mon. Fd.- 3¼" Brass cap on a 2½" O.D. iron pipe, protrudes 2" above ground. 1957

Bt's Fd.- 20" now 51" dia. 5' high D.Fir stump, with a previously opened blaze, scribing visible "25S", bears S.39°E., 79.2' (agrees with rec.) OBT

40" now 70" dia. 10' high broken D.Fir snag, with a healed blaze, bears S.19°W., 17.8' (agrees with rec.) OBT

(Cont. Next Page)

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 700300

PRIMARY CORNER DESCRIPTION Sec. cor. for 19 & 30; 24 & 25, T25-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

15" now 18" dia. D.Fir, with a fully healed single blaze, bears N.16½°E., 135.6' (agrees with rec.) 1957

9" now 18" dia. 2' high rotting cedar stump, with a fully healed blaze, bears S.75°E., 131.1' (rec. S.75°E., 132.7') 1957

45" now 36" dia. 2' high rotting D.Fir stump, with scribing visible "T25S", bears N.33¼°W., 37' (agrees with rec.) 1957

Found an 11" dia. D.Fir, with a fully healed double blaze, bears N.67¼°W., 75' (agrees with 1982 BLM BT tag).

New Accessories -

13" dia. D.Fir single blazed and scribed "T25S R4W S30 CS Bt", bears S.33°E., 8.3'

18" dia. Maple, double blazed and scribed "T25S R5W S24 CS BT", bears N.43½°W., 14'.