

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec Cor for 16, 17, 20, & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Elder & Gile, Contract #31 dated April, 1853 (DCSO records, Vol. 9 page 3835).

Set post cor. to secs. 16, 17, 20 and 21 from which
A Y.Oak, 10" dia. bears N.59½°E., 130 lks. dist.
A Y.Oak, 14" dia. bears N.51°W., 149 lks. dist.
A Y.Oak, 9" dia. bears S.11°E., 81 lks. dist.
A Y.Oak, 10" dia. bears S.71 3/4°W., 110 lks. dist.

Looked for not fd, DCSO Jan. 1962 - C.S. File 49/123-58

Russ Dodge, surveyed for Conrad Jones, Apr. 1996 - M125-1

Set - by proportionate measurement - 5/8" x 30" iron rod,
w/plastic cap stamped HGE INC.
New Accessories -
12" D.Fir, N.50°W., 28.1 ft. scribed "S17 BT"
12" D.Fir, S.22°W., 24.8 ft. scribed "S20 BT"
10" D.Fir, S.18°E., 24.8 ft. scribed "S21 BT"
8" Twin Oak, N.30°E., 11.3 ft. scribed "S16 BT"

Fd to be out of position by C. Sweeden, - Aug. 1998 - M130-22

Russ Dodge, corrective survey for Conrad Jones, Sept. 1998
survey replaces M125-1.

Set - 5/8" x 30" iron rod w/plastic cap stamped HGE INC
Accessories -
12" D.Fir, N.30°W., 35.1 ft.
12" D.Fir, S.29°W., 10.5 ft.
10" D.Fir, S.50°E., 16.3 ft.
8" Twin Oak, N.25°E., 25.3 ft.
Note - An error was discovered in our original survey M125-1.
This survey shows all new information, the old monuments
were pulled by our firm and new corrected monuments
established.

DCSO-GIS Corner visitation - 7/1/2004 - Typed: 1/24/2011 -
C.S. File 67/33-1

Monument - 5/8" rebar.
Comment - OK