

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec Cor for 3 & 4; 33 & 34 of T24-6

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - Elder & Gile, Contract #31 dated April, 1853
(DCSO records, Volume 8 page 3132)

Set post cor. to secs. 33, 34, 3 and 4, from which
A W.Oak 12" dia. bears S.12°E., 42 lks. dist.
A B.Oak 15" dia. bears S.57°W., 125 lks. dist.
A Laurel, 15" dia. bears N.39°W., 110 lks. dist.
A B.Oak 12" dia. bears N.0°15'E., 60 lks. dist.

G.G. Stewart, For J.A. & Fay Leatherwood, March, 1922
C.S. File 2/14 and Volume 3 Page 112

Reset from one O.B.T. Others down.
Set 1¼" I. Pipe. Remarkd:
14" Fir N.14°E., 16.8 ft.
16" Fir N.16°W., 9.2 ft.
36" Fir S.37°E., 136.2 ft.
4" Fir S.48°W., 46.8 ft.

Milo E. Godfrey, Deputy Co. Surveyor, Vernon Tracy; Mike
Stone - November 1962 - C.S. File 49/123-43

Found - 1¼" I.P. set by Stewart.
Fir tree, now 26" N.16°W., 9.2 ft. (to face)
scribing visible on pitched over face.
Stump hole & portions of Fir roots N.14°E., 16.8 ft.
Rotted Fir stump S.37°E., 136.2 ft. bark gone, no
scribing.
Rotten Fir stump S.48°W., 46.8 ft. opened & found
good scribing.
Stump hole & fragments of Laurel roots N.39°W., 72.6
ft. (original)
Stump hole with B.Oak growing out of one side
N.¼°E., 39.6 ft.
No trace found of other original BT.
DID NOT SET BRASS CAP.
New BTs - 12" W.Oak S.74°W., 63.5 ft. mkd. T25S R6W S4 CS BT.
11" D.Fir N.28°E., 35.4 ft. mkd. T24S R6W S34 CS BT
7" W.Oak S.32°E., 9.5 ft. mkd. T25S R6W S3 CS BT.
Corner lies in a N. & S. fence line.

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec Cor for 3 & 4; 33 & 34 of T24-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent Resurvey, June 5-21, 1972, Albright & Bowder
(DCSO records, Volume 36 Pages 14998-99)

The cor. of secs. 3, 4, 33 and 34, perpetuated and recorded
by G.G. Stewart, Deputy Co. Surveyor, in 1922, when original
corner evidence was still existent, monumented with an iron
pipe 1½" dia. firmly set, extending 8" above ground, from
which bearing trees mkd. by Stewart:

A decayed Fir stump, size indeterminate, bears S.48°W.
71 lks. dist. with scribe marks 4 BT visible on
open blaze.

A Fir 30" dia. bears N.16°W., 15 lks. dist. with healed
blaze.

and bearing trees mkd. by the County Surveyor in 1962:

A Fir 21" dia. bears N.28°E., 54½ lks. dist. with healed
double blaze.

A W.Oak 9" dia. bears S.32°E., 14 lks. dist. with healed
blaze.

A W.Oak 13" dia. bears S.74°W., 98 lks. dist. with healed
blaze.

At the corner point:

Set an iron post, 28" long 2½" dia. 24" in the ground,
directly atop iron pipe, with brass cap mkd.

T 24 S R 6 W
S 33 | S 34
S 4 | S 3
1972

The corner point is located in a wire fence, extending N & S.

Found OK June 1994 by K. DeGroot - M119-34.

Found OK by Douglas Co. Surveyors Office - Randall W. Smith
& Stephen J. Flause - 1/29/1998 - C.S. File 64/79-9

Fd. OK by Les Roberts - March 2000 - M134-38

Fd. OK by M. Heimbürger, Nov. 2001 - M139-16

DCSO-GIS Corner visitation - 6/30/2004 - Typed: 1/25/2011 -
C.S. File 67/33-1

Monument - 2.5" BC/IP
Comment - OK

Fd. Ok by Mark Heimbürger, 2/2013 - M164-60