

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 & 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Henry S. Gile, Contract #31 dated April, 1853  
(DCSO records Volume 9 Page 3824)

-----  
Set post cor. to secs. 14, 15, 22 and 23, from which  
A Y.Oak 30" dia. bears N.52°E., 17 lks. dist.  
A Y.Oak 18" dia. bears S.23½°W., 102 lks. dist.  
A Y.Oak 18" dia. bears N.68°W., 38 lks. dist.  
A W.Oak 40" dia. bears S.33°E., 53 lks. dist.

F.C. Frear, for: Joe Large & Scott Henry - April, 1918  
C.S. File 2/5; Field Book 43 Page 66; Vol. 3 Page 45

-----  
Renew from old Govt. BTs - Set in 1½" x 30" galv. iron  
pipe, from which  
All old Gov. corners bear as given. I remarked all old  
trees.

Milo E. Godfrey, Deputy - Vernon Tracy; Mike Stone  
August 1962 - C.S. File 49/123-20

-----  
Found - 1" pipe set by Frear at corner.  
Badly rotted & burned Oak snag N.52°E., 11.2 ft.  
scribing visible.  
B.Oak now 24" n.68°w., 25.1 FT. shows faint scar.  
B.Oak now 30" S.23½°W., 67.3 ft. shows fairly plain  
scar.  
W.Oak now 44" S.33°E., 35.0 ft. cut open & found  
reverse orig. scribing.

Set brass cap at cor. mkd: County Surveyor's T25S R6W  
Office 1962      S15 | S14  
                             S22 | S23

New BTs - 18" B.Oak S.52°E., 13.0 ft. mkd. T25S R6W S23 CSBT  
9" Madrone S.70°W., 41.0 ft. mkd. T25S R6W S22 CSBT  
9" W.Oak N.10°W., 14.8 ft. mkd. T25S R6W S15 CSBT  
6" W.Oak N.46°E., 18.2 ft. mkd. S14 CS BT.

Corner lies in old E. & W. fence line approx. 40 ft. west of  
ridge top.

Douglas Co. Surveyors Office - Karen Reed; Terrie Plouff;  
Teresa Buley - Oct. 14, 1980 - C.S. 61/11-31

-----  
Found - 1962 DCSO brass cap on a 1" I.P. protruding 0.8 ft.  
above ground, properly marked.  
An orig. 18" Y.oak now a 30" x 4.5 ft. stump bears  
N.68°W., 25.1 ft.  
An orig. 18" Y.Oak now a 30" B.Oak bears S.23½°W.,  
67.3 ft. Paint scar visible.      CONT. NEXT PG

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Cor. Secs. 14, 15, 22 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An orig. 40" W.Oak still 40" bears S.33°E., 36.6 ft. (Rec. 35.0 ft. this is a face measurement) Tree has been previously chopped out faint scribe marks visible.  
An 18" B.Oak now 21" with healed over double blaze bears S.52°E., 13.0 ft.  
A 9" Madrone, now an 11" with well healed double blaze bears S.70°W., 41.8 ft. (Rec. 41.0 ft.)  
A 9" W.Oak still 9" with well healed double blaze bears N.10°W., 14.8 ft.  
A 6" W.Oak now 7" with well healed double blaze bears N.46°E., 18.2 ft.  
Left cap in place. Tagged all BTs.  
Corner lies 1.7 ft. N. of an E-W fence approx. 40 ft. west of ridge top. 1" I.P. set by Frear not found.

Found OK by B Shaner, July 1997 - M 124-59 & C.S. 65/15-10 C

Ken Hoffine, Lone Rock Timber - For: Oregon Pacific west Development LLC - May 2012 - M163-60  
-----  
Found brass cap marked County Surveyors Office 1962 - BTs as recorded - Corner lies 1.7 ft. North of an East West fence line approx. 0.8 ft. above ground level.