

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14, & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
(DCSO records, Volume 9 Page 3825)

-----  
Set post cor. to secs. 10, 11, 14 and 15, from which  
A Y.Oak 14" dia. bears S.14¼°E., 202 lks. dist.  
A Y.Oak 16" dia. bears S.83°W., 50 lks. dist.  
A Y.oak 28" dia. bears N.8°W., 41 lks. dist.  
A Y.oak 16" dia. bears N.26°E., 143 lks. dist.

Milo E. Godfrey, Dep. Co. Surveyor - Vernon Tracy; Mike Stone  
August, 1962 - C.S. File 49/123-21

-----  
Found - 5/8" Iron rod at corner, not recorded.  
Rotted remnants of Oak snag N.8°W., 27.1 ft. Good  
reverse scribing.  
B.Oak now 31", S.14¼°E., 133.3 ft. shows very plain  
scar.  
B.Oak now 36", S.83°W., 33.0 ft. shows faint scar,  
tree dying.  
Rotten Oak, down, N.26°E., 94.4 ft. badly rotted,  
reverse scribing.  
Set brass cap at cor. mkd: County Surveyor's T25S R6W S10|S11  
Office, 1962 S15|S14  
New BTs - 11" W.Oak N.58°W., 38.6 ft. mkd: T25S R6W S10 CS BT.  
28" double B.Oak (measured below fork), S.22°W., 59.7  
ft. mkd: T25S R6W S15 CS BT.  
20" B.Oak S.34°E., 33.4 ft. mkd: T25S R6W S14 CS BT.  
21" W.Oak N.84°E., 65.6 ft. mkd: T25S R6W S11 CS BT.  
Fence corner, fences E. & N., bears N.15°W., 4.0 ft.