

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 2/5/98 - C.S. File 64/79-23

Found - 2½" dia., brass cap on a 1½" O.D. iron pipe, protrudes 10" above ground. 1962
No OBTS found.
16" Fir, now root hole, bears N.63°E., 32.0 ft. (Agrees with rec.) 1922
18" now rotted D.Fir remains, bears S.59°W., 15.6 ft. (Agrees with rec.) 1922
4" now 7" dia., Madrone with a fully healed double blaze bears S.81°E., 36.4 ft. (Rec. N.78°E., 36.4 ft) 1962
18" now 26" dia. D.Fir, with a fully healed double blaze, bears S.30°W., 93.0 ft. (Rec. S.33°W., 93.0 ft) 1962

New BTs- 7" dia. B.Oak, double blazed and scribed "¼ S2 CS BT", bears S.58½°E., 15.9 ft.
5" dia., D.Fir, double blazed and scribed "¼ S3 CS BT", bears S.58½°W., 9.5 ft.

Note - Corner lies at a fence corner with old fence running North & West. See sketch in file.

Found OK by K. Hoffine, Mar. 2000 - M134-64

DCS0-GIS Corner visitation - 6/30/2004 - Typed: 1/25/2011 - C.S. File 67/33-1

Monument - BC/IP 1.25"
Comment - ok