

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Elder & Gile, Contract #31 dated April, 1853  
(DCSO records, Volume 9 Page 3826)

-----  
Set ¼ sec. post, from which  
    A W.Oak 24" dia. bears N.79¾°E., 1150 lks. dist.  
    A W.Oak 18" dia. bears S.79¾°W., 706 lks. dist.

F.C. Frear, Co. Roadmaster - J. Wolford; P.D. Wolford;  
B. Lane - November 22, 1932 - "Old" Cor. renewal book, Page  
56 - (I could not find any other record source for this info,  
V. Laugen, Sept. 1991)

-----  
Re-set from 1 old BT, marks plain.  
Set 1¾" x 30" I. Bolt with nut from which:  
    A 24" W.Oak bears S.75½°W., 548.0 ft.  
    A 30" W.Oak bears S.57¼°E., 685.0 ft. Gone.  
A Plowshare East 150.0 ft. set 4/11/47, Frear.

Searched for, not found.  
Found no trace of orig. cor. or renewal recorded. I do not  
believe this cor. was renewed in 1932. No evidence fd. of  
renewal - to the S.W. - in the general area of renewal BT. Fd.  
several small Oak stumps that look to be as old as time of re-  
newal. No trees or stumps fd. in that area anywhere near big  
enough for renewal BT. No field fence - or old evidence of  
former fence line - exists within 150 ft. of probable location  
of corner. This renewal must refer to some other township,  
or at least some other corner.  
Milo E. Godfrey, November 16, 1962 - C.S. File 49/123-42