

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 044030

PRIMARY CORNER DESCRIPTION Int. L. Cor. Churchill DLC #44

Alias 048040 Description E SE Cor. DLC #48
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Contract #63 dated Mar. 22, 1856

Set a post as per instructions, from which
An Alder 24" dia., bears N.30°W., 58 lks.

C.C. Boyer, for L.T. Thompson, May 2, 1913 - Field Book
61 Page 55

Old trees destroyed. Marked new tree:
A W.Oak 6" dia., N.85°W., 26.85 ft. marked C. 48
T.25 S. R. 7 W. B.T.

Searched for, not fd. M.S. - April 15, 1966, C.S. 54/10-3

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - C.S. 64/69-8 - June 20, 1996

Corner searched for and not found
Note: Creek called out in DLC line notes, appears to have
widened out on east bank.