

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 048020

PRIMARY CORNER DESCRIPTION NW Cor. Thrasher DLC #48

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>Original - Dennis Hathorn, Contract #63 dated Mar. 22, 1856 ----- Set post, as per instructions, from which     A B.Oak 18" dia., bears S.50°E., 48 lks.</p>
<p>Bruce Rogers, Deputy; W.S. &amp; M.S. - May 1965 - C.S. 54/10-1 ----- Found - Orig. 18" B.Oak, down &amp; rotted, tree opened &amp;         scribing visible. (stump hole by Oak fits                             bearing &amp; distance S.50°E., 31.7 ft.)         Squared stake at corner, not original. Set Brass cap at cor. mkd: County Surveyor's Office, <u>1965</u>   N.W. Cor. DLC 48 T25S   R7W New BTs - 14" Cedar S.7°W., 18.3 ft. mkd. N.W. DLC 48 CS BT.           25" D.Fir N.7°E., 8.8 ft. mkd. N.W. DLC 48 CS BT.</p>
<p>Douglas County Surveyors Office - Randall Smith &amp; Stephen Flause - July 18, 1996 - C.S. 64/69-11 ----- Found - 2½" Dia. Brass cap on a 1½" OD iron pipe, protrudes         8" above ground.         Rotted wooden post with tack in top protrudes 8"         above ground, .5' east of BC/IP. BTs Fd - 18" B.Oak now root hole, bears S.50°E., 31.7'.         20" dia. I.Cedar, with a fully healed double blaze,                 bears S.7°W., 18.3'.         29" dia. D.Fir, with a fully healed double blaze,                 bears N.7°E., 8.8'. New BTs- 14" dia. D.Fir double blazed and scribed "NW DLC 48                 CS BT" bears S.76½°E., 29.2'.         13" dia. Pistol Butt maple, double blazed and                 scribed "NW DLC 48 CS BT", base of scribed                 trunk bears N.62°E., 37.3'. Corner lies north 2.5' from an east-west fence line</p>
<p>FD. Ok by D. Edwards, 7/2006 - M151-13</p>
<p>Fd. as per record &amp; set 6 ft steel post 2 ft south 4/2018 - by D. Edwards M174-20</p>
<p> </p>