

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec. cor. for 19 & 30; 24 & 25 of T25-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W. H. Byars, under Contract #202 dated March 11, 1874 (DCSO records, Vol. 9 Page 3890)

Set post (Fir) for the cor., from which
A Fir 60" dia., bears N.82°E., 25 lks. dist.
A Fir 60" dia., bears S.8°E., 69 lks. dist.
A Fir 14" dia., bears S.82°W., 24 lks. dist.
A Fir 14" dia., bears N.32½°W., 22 lks. dist.

GLO survey by A.R. & S.C. Flint, 1881, found Post and witness trees in good condition. (DCSO records Vol. 9 Pgs 3897-98)

BLM resurvey by Beck & Jelley - Group # 563 Survey 1964 (DCSO records, Volume 33 Page 13741)

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set a Iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd:

T	25	S
R 8 W		R 7 W
S 24		S 19
S 25		S 30

1964

from which
A Fir 23" dia., bears N.48½°E., 32 lks. dist., mkd.
T25S R7W S19 BT.
A Fir 23" dia., bears S.18¼°E., 45 lks. dist., mkd.
T25S R7W S30 BT.
A Fir 19" dia., bears S.47½°W., 30 lks. dist., mkd.
T25 S R8W S25 BT.
A Fir 16" dia., bears N.82½°W., 37 lks. dist., mkd.
T25S R8W S24 BT.

Fd Ok by Ronald Geisler, L.S. 1988 - For: Champion International Corp. - April/June 1983 - M 94-31