

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, Contract #73 dated June 8, 1857 (DCSO records, Vol. 9 Page 3881)

Set ¼ sec. post, from which
 An Oak 18" dia., bears S.48°E., 99 lks.
 An Oak 12" dia., bears N.45°E., 19 lks.

H. Germond, For: McKay and Lawrence - December 18, 1899
Volume 2 Page 83

Set sandstone 18 x 8 x 4 inches.

BLM resurvey by Lynn Roseberry, under Group #645 - Survey, July 1967/Sept. 1968 (DCSO records, Volume 36 Pg. 14964)

The ¼ sec. cor., determined at record bearing and distance from the original bearing trees:
 An Oak 23" dia., bears N.45°E., 19 lks. dist., with scribe marks 16 visible in negative, on overgrowth of opened and rotted blaze.
 A root hole, bears S.48°E., 99 lks. dist., with an uprooted Oak, 28" dia., alongside, with no marks visible.

At the corner point
Set a Iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd: T 25 S R 7 W

¼ $\frac{S\ 16}{S\ 21}$
1968

from which new bearing trees
 A Fir 12" dia., bears N.75°W., 27½ lks. dist., mkd. ¼ S16 BT.
 An Oak 12" dia., bears S.24¾°E., 42½ lks. dist., mkd. ¼ S21 BT.

Doug. County Surveyors Office - Randall Smith; Stephen Flauser
November 17, 1989 - C.S. File 64/3-3

Found - 1968 BLM brass cap on a 2½" O.D. Iron pipe, protruding 8" above ground.
 12" now 24" dia. W.Oak, illegible reverse scribe marks seen from a previously opened unhealed blaze, bears N.45°E., 12.5 ft. (Orig. BT)

(Cont. Next Page)

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 16 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

18" Oak, now a root hole. An approx. 30" dia. rotted uprooted and down Oak, no blazes or scribing seen (did not open), found approx. 10 ft. down hill of root hole. Root hole bears S.48°E., 65.3 ft. (Orig. BT)

12" now 17" dia. 1 ft. high D.Fir stump with an illegible scribe mark found, bears N.75°W., 17.4 ft. (Rec. N.75°W., 18.2 ft.) (1968 BLM)

12" now 12" dia. W.Oak with a fully healed single blaze bears S.23½°E., 27.3 ft. (Rec. S.24¾°E., 28.0 ft.) (1968 BLM resurvey)

New BTs - 8" dia. pistol-butt D.Fir double blazed & scribed "¼ S21 CS BT" bears S.49½°E., 12.3 ft.

12" dia. W.Oak double blazed and scribed "¼ S16 CS BT" bears N.32½°W., 22.2 ft.

Corner lies on a steep Southwest slope.

Fd. OK by K. DeGroot, Dec. 1999 - M133-76
Fd. Ok by David Edwards, July 2001 - M 138-39

FD. as BC as per record by Kris DeGroot 3/2014 - M167-44
NAD 83 (2011) Lat: 43°23'20.24791"N Long: 123°32'09.55413"W

2