



TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor for Secs. 33 and 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas County Surveyors Office - Randall Smith & Stephen  
Flause - July 8, 1996 - C.S. 64/69-12

-----  
Found - 3¼" dia. Brass cap on a 2½" O.D. iron pipe  
          protruding 10" above ground.  
          1" dia. axle with a 3" dia. gear protruding 10"  
          above ground, is along westerly edge of BC/IP.  
BTs - 35" dia. B.Oak, with a fully healed double blaze,  
          bears N.1°E., 59.4'.  
      31" dia. B.Oak, with a fully healed double blaze,  
          bears N.24 ¾°W., 66.7'.  
New BTs- 20" dia. D.Fir, double blazed and scribed "¼ S34 CS  
          BT", bears N.74½°E., 12.3'.  
      17" dia. D.Fir, double blazed and scribed "¼ S33 CS  
          BT", bears N.11 ¾°W., 70.8'.  
Corner lies in an east-west fence line

FD. Ok by D. Edwards, 7/2006 - M151-13

Fd. as per record except that the Fir N.11¾°W., is now a 20"  
dia., stump & set 6 ft steel post 2 ft N.89°W. - 4/2018 - by  
D. Edwards M174-20