

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, Contract #63 dated
March 22, 1856 (DCSO records, Vol. 9 Page 3862)

Set Post cor. secs. 26, 27, 34 and 35, from which
A B.Oak 12" dia., bears S.47°W., 121 lks.
A B.Oak 20" dia., bears S.55°E., 97 lks.
A B.Oak 15" dia., bears N.65°E., 42 lks.
A B.Oak 12" dia., bears N.20°W., 51 lks.

BLM resurvey by G. Steven Popken, uner Group #869 - Survey
May/July 1975 (DCSO records, Volume 37 Pages 15304-05)

The Sec. cor., determined at record bearing & distance from
the remains of the original bearing trees:

A decayed Oak stump, size indeterminate, bears
N.65°E., 42 lks. dist., no marks visible.
A decayed Oak stump, size indeterminate, bears
S.47°W., 121 lks. dist., no marks visible.
A B.Oak 38" dia., bears N.20°W., 51 lks. dist.,
with fragmentary scribe marks visible on
opened blaze.

At the corner point

Set a Iron post, 28 ins. long, 2½ ins. diam., 42 ins. in the
ground, with top 14" below surface, with brass cap mkd:

T 25 S R 7 W
S 27 | S 26
S 34 | S 35
1975

from which new bearing trees

A Fir 11" dia., bears N.56°E., 168 lks. dist.,
mkd. T25S R7W S26 BT.
A B.Oak 34" dia., bears S.16½°E., 422 lks. dist.,
mkd. T25S R7W S35 BT.
A Fir 13" dia., bears N.29½°W., 225 lks. dist.,
mkd. T25S R7W S27 BT.

No suitable tree available within limits in SW Quadrant

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - June 18, 1996 - C.S. 64/69-6 - Cond. report only

Mon. Fd.- 3½" dia. Brass cap on an iron pipe is found 12"
below ground.

BT's Fd.- 45" dia. B.Oak, with a previously opened unhealed
blaze no scribing visible, bears N.18°W.,
32.3'.

(Cont. Next Page)

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

15" dia. B.Oak, now roothole found near rec. BRG. &
DIST.
no evidence of any other OBT's Found
15" dia. D.Fir, with a fully healed single blaze,
bears N.56°E., 109.8'.
18" dia. D.Fir, with a fully healed single blaze,
bears N.29½°W., 148.5'.
46" dia. B.Oak, with a fully healed single blaze,
bears S.16½°E., 278.5'.