

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 638300

PRIMARY CORNER DESCRIPTION M.C. between Secs. 24 & 25

| | |
|---------------------|--|
| Alias <u>860140</u> | Description <u>M.C. Rt. bk. N. Umpq. River</u> |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Original - Dennis Hathorn, Contract #63 dated Mar. 22, 1856
(DCSO records, Volume 9 Page 3860)

Set Meander Post, from which
 A B.Oak 18" dia., bears N.26°E., 16 lks.
 A B.Oak 20" dia., bears S.40°E., 90 lks.

Ben B. Irving, D.C.S. Wit: N.E. Richardson; R.L. Irving
C.S. File 37/82; - Dec. 12, 1932

From measurement from ¼ sec. cor. and O.B.T. as originally
recorded in gov't field notes. Drove a 1" x 48" Iron pipe
and remarked the O.B.T. 40" B.Oak N.26°E., 16 lks.
This tree is the same as is used as a BT for the sec. cor.

Doug. County Surveyors Office - Milo Godfrey, Deputy - Mike
Stone - Aug. 1963 - C.S. File 49/76-26

Found BT (Orig) remarked by BBI in 1932 - other BT gone.
Iron pipe set by BBI washed out by river.
Corner not renewed - position for cor. Now below high bank -
would have necessitated setting wit. cor. - ¼ cor. (Renewed)
is only approx. 80 ft from MC - I did not feel justified in
setting WC to MC so near to ¼ cor.