

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Morris Wygant, Compassman for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 10 Page(s) 3995)

Set a fir post, 3 ft. long 4" sq. 24" in the ground for 1/4 sec. cor., marked 1/4 S29 on N & 32 on S face from which
A fir, 24" dia., bears S.85°30'E., 89 lks., mkd: 1/4 S32 BT.
A fir, 36" dia., bears N.83°30'E., 30 lks., mkd: 1/4 S29 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Sept 1968 - C.S. File 54/72-40

Found - Orig. 36" now 48" Fir, N.83 1/2°W., 13.2 ft. (rec. N.83 1/2°E.) opened & find scribe & reverse under 56 rings of overgrowth.
Large hole bears S.85 1/2°E., 58.7 ft., no trace of tree, extremely steep slope.
No evidence that there ever was a tree N.83 1/2°E., 13.2 ft.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T25S R8W
OFFICE 1/4 S 29
1968 S 32

New BTs- 13" Hemlock N.39°E., 12.7 ft. mkd: 1/4 S29 CS BT.
9" D.Fir S.13°E., 9.2 ft. mkd: 1/4 S32 CS BT.
Ridge call to west fit very well with orig. call distances. This corner lies on very steep easterly slope about 200' E of ridge, course NW & SE.

Tony Hostetter - For: Weyerhaeuser Co. - Feb. 2018 - M174-25

Found - 1968 DCSO brass cap, monument is lying on ground out of position.

Set - A 5/8"x36" IR with plastic cap marked "HOSTETTER LS 1975" based on 1968 BT which bears N.39°E., 12.7 ft to center (14" Hemlock, face evident)

Found - 48" decayed fir stump, OBT, no marks, bears; N.83°W., 13.2 ft to center. (Rec. N.83 1/2°W.)

New BTs- 23" Hemlock, scribed "S32 1/4 BT", BT tag bears; S.03°20'E., 17.0 ft to spike.
9" Hemlock, scribed "S 29 1/4 BT", BT tag, bears; N.04°55'W., 19.5 feet to spike.