

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, & 32, only (East)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Morris Wygant, Compassman for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 10 Page(s) 3995-6)

At point of intersection, I set a cedar post, 3 ft. long 4" sq. 24" in the ground for closing cor. for secs. 29 & 32, marked CC T25S R8W on W., S 32 on S and S29 on N faces; with 1 groove on S & 5 grooves on N faces; from which

A fir, 30" dia., bears S.80"W., 8 lks. mkd T26S R8W S32 BT
A fir, 12" dia., bears N.34°40'W. 32 lks. mkd T25S R8W S29 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Sept 1968 - C.S. File 54/72-36

Found - Remains of old scribed post at corner.
Orig. 30" Fir, now 36" Snag, S.80°W. 5.3 ft., open & shows scribe.
In approx. locus of NW BT., only decayed remains of low stump.

Set - Brass Ca at Cor mkd: COUNTY SURVEYORS T25S R8W
OFFICE CC S 29
1968 S 33

New BTs- 13" Hemlock N.38°W., 22.5 ft. mkd: T25S R8W S29 CC CS BT.

7" Hemlock S.54°W. 20.8 ft. mkd: S32 CC CS BT.

This corner lies on very steep N slope, about 204 ft. south of sec corner to sections 28 & 33, record distance 198 ft

BLM dependent resurvey by James E. Jelley & Jack W. Bowder, Cadastral Surveyors, under Group #767, surveyed April/May 1972 - (DCSO records Vol. 36 Page(s) 15038-9)

The original closing corner of sees. 29 & 32, on the W bdy. of sec. 33, perpetuated & recorded by Tracy, in 1968, monumented with an iron post, 1" diam., firmly set, projecting 18" above ground, alongside of which the decayed remains of the original corner post, with brass cap (properly) mkd.

from which the remains of the original BTs

A fir snag, 36" dia., bears S.80°W., 8 lks., with fragmentary scribe marks visible on open blaze.

and BTs mkd. by Tracy

A hemlock, 8" dia., bears S.54°W., 31 lks., with scribe marks 532 CCCS visible on partially healed blaze.

A hemlock, 13" dia., bears N.38°W., 33 lks., with scribe marks T25S R8W S29 CCCS BT visible on open blaze.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, & 32, only (East)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

and a BT of which I have no record
A fir, 5" dia., bears N.19°W., 45 lks., with a galvanized nail, with "W" embossed on the head, driven into base.

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - Oct. 12, 1988 - C.S. File 62/59-6

Found - 1968 County brass cap on a 1¼" 0.0. iron pipe 36" long out of ground and out of position on a steep hillside. Monument set in 1968. No evidence of 1911 cedar post found.

Orig. BT, a 30" fir, now a 36" DBH D. fir snag with a previously opened blaze, showing a "2" and other illegible scribing, bears S.80°W., 5.3 ft. (per orig. rec.) Other OBT not found.

A 13" Hemlock now a 16" DBH hemlock with a partially healed single blaze revealing illegible scribe marks bears N.38°W. , 21.8 ft. (as per BLM resurvey record) 1968

A 7" Hemlock now an 8" DBH Hemlock with a fully healed single blaze bears S.54°W., 20.8 ft. (as per 1968 Ren.)

A previously unrecorded BT fd. in BLM resurvey, bearing N.19°W., is gone, possible removed by logging.

A previously unrecorded corner reference, a 40" dia. 24" tall D.Fir stump cut as a logging cable anchor with no evidence of blazes or scribing bears N.18½°W. 30.4 ft. (metal tag on stump rec. bearing & dist. as N.16½°W., 28.4 ft.)

Set - The corner position as determined from the found BTs is monumented with a PK nail driven into a small ledge of bedrock chiseled out for this purpose. Directly plumb over the above PK nail is set the found brass cap monument with added marks "RESET 1988". A rough mound of stone is built up around the BC. Monument now protrudes 7' above mound of stone.

Corner lies on steep northerly slope near crest of easterly running spur ridge. Corner is in old growth timber near edge of recent clear cut.