

TOWNSHIP 25½ RANGE 01E POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 34 (N) only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Otto L. Draper, US Transitman, under Special Instructions dated March 12, 1921, surveyed Aug/Oct. 1928 - (DCSO records Vol. 22 Page(s) 9232-3)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for ¼ sec. cor. of sec. 34 only, with brass cap marked

¼ S 34
1928

from which

A cedar, 10" dia., bears S.25°E., 49 lks., mkd: ¼ S34 BT.
A fir, 8" dia., bears S.15°W., 30 lks., mkd: ¼ S34 BT.

John Ransom, USFS - Done by: Hillman - 1/2015 - C.S. File 65/89-22

Found - 1" dia., galvanized iron pipe bent to the ground with a 2½" dia, brass cap (properly mkd). **I removed and straightened** the iron pipe and replaced it in the exact position flush in a 24" dia., collar of stone.

15" fir snag, S.15°W., 19.8 ft., axe work and fragmentary scribe marks.

New - Indt. fir stump, S.25°E., 32.3 ft. none (markings)
14" cedar brs. S.65°E., 34.7 ft. marked "¼ S34" "BT" on a double blaze.

17" D.Fir brs S.4°E., 31.4 ft. marked ¼ S34" "BT" on a double blaze.

13" Hemlock brs N.20½°W., 17.7 ft. mkd: "X" "BT" on a double blaze.

10" D.Fir brs N.79°W., 4.6 ft. mkd: "X" "BT" on a double blaze.

Placed an alum. guard post with monument sign 2 ft. North of the monument.

Note - The corner is on a ridge 105 ft East of Forest Road 4713 and ¼ mile north of the junction with Forest Road 4713-300.

Measurements made with staff compass (15¾°E decl.) and a steel tape.