

TOWNSHIP 26 RANGE 01E POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Otto L. Draper, US Transitman, under Special Instructions dated Dec. 24, 1920 - (DCSO records Vol. 22 Page(s) 9596)

-----  
Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor., with brass cap marked

1/4  $\frac{S\ 21}{S\ 28}$   
1928

from which

A cedar, 14" dia., bears N.11°E., 18 lks., mkd: 1/4 S21 BT.  
A hemlock, 14" dia., bears S.21°W., 71 lks., mkd: 1/4 S28 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - D. Schultze - 6/27/1972 - C.S. File 54/94-112

-----  
Found - 1928 GLO Brass Cap, out of ground & bent. We straighten Pipe & Reset at Corner Point from one remaining BT as follows:

Orig. 14", now 20" Cedar, N.11°E., 11.9 ft., alive, good scribing, "1/4 S21 BT" on unhealed blaze.

New BT - 24" Cedar S.20°W., 60.9 ft., scribed "1/4 S28 CS BT"  
This BT is across creek from cor. which lies about 150 feet East of USFS Road #2636.