

TOWNSHIP 26 RANGE 02E POINT IDENTIFIER # 942050

PRIMARY CORNER DESCRIPTION Cor. No. 5 HES 142

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>HES No. 142 by Frank D. Maxwell, Forest Service Surveyor, under special instructions dated April 27, 1914 - Surveyed July 1914 - DCSO records Vol. 28 Page(s) 12166-7)</p> <p>-----</p> <p>Cor. No. 5, identical with cor. H/5 of listing survey, a post mkd. and witnessed as described by G.A. Bonebrake, Forest Ranger; in place of which, I set a basalt stone, 24x12x10", 14" in the ground, for cor. 5, mkd. 5 HES 142 on NW face, with a cross (+) on top, from which</p> <ul style="list-style-type: none"><li>A fir, 15" dia., bears N.74°20'E., 35 lks.</li><li>A fir, 10" dia., bears N.89°00'W., 25 lks.</li></ul> <p>Both trees blazed &amp; scribed 5 HES 142 BT. Pit and mounds impracticable at this and all other cors.</p>
<p>GLO Survey by Otto S. Draper, U.S. Transitman, under Special Instructions dated Dec. 24, 1920, surveyed Sept. 1929/Aug. 1930 - (DCSO records Vol. 23 Page(s) 9724</p> <p>-----</p> <p>Cor. No. 5 HES 142, which is determined by orig. BTs; in middle of road.</p> <ul style="list-style-type: none"><li>A fir, 16" dia., bears N.71°E., 35 lks., mkd. 5 HES 142 BT</li><li>A fir, 14" dia., bears S.88°W., 25 lks. mkd. 5 HES 142 BT</li></ul>
<p>Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey &amp; Clete Putnam - Aug. 6, 1960 - C.S. File 52/43-2</p> <p>-----</p> <p>Found - Orig. 15" now 24" fir stump N.74°20'E., 23.1 ft. We open &amp; find good scribing "142 BT"</p> <ul style="list-style-type: none"><li>Orig. 10" now 24" fir checks bearing &amp; distance for NW BT.</li></ul> <p>Corner at east edge of roadway - corner stone not fd. Set brass cap at corner mkd: COUNTY SURVEYORS OFFICE 1960 CORNER No. 5 HES 142 T26S R2E</p> <p>New BTs- 8" R.Fir bears N.20°E., 30.8 ft. scribed 5 HES 142 CS BT. 10" R.Fir bears S.77½°W., 21.4 ft. scribed 5 HES 142 CS BT.</p>
<p>DCSO (VRT) Fd. OK 10/1969 - C.S. File 52/43-7</p>
<p>Robert Dean, LS 1808 - For: USFS -Dec. 20, 1984 - M98-6 &amp; C.S. File 58/204-11</p> <p>-----</p> <p>Found - 1" galv. I.P. with 2½" brass cap in 36" cairn. 1960. From Which: A 33" D.Fir stump, previously opened face visible, bears N.86°25'W., 16.2 ft. (Rec. N.89°W., 16.5 ft. per HES 142) continued next page</p>

TOWNSHIP 26 RANGE 02E POINT IDENTIFIER # 942050

PRIMARY CORNER DESCRIPTION Cor. No. 5 HES 142

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

	A 16" D.Fir stump, portion of face visible, bears N.17°20'E., 30.4 ft. (Rec. N.20°E., 30.8 ft. per 1960 Ren.)
	A 23" rotted D.Fir stump bears N.73°05'E., 23.9 ft. (Rec. N.74°20'E., 23.10 ft. per HES 142)
	A 16" D.Fir, good scars, bears S.76°12'W., 21.4 ft. (Rec. S.77½°W., 21.4 ft. per 1960 Ren.)
New BT-	A 7" D.Fir, scribed "5 HES 142 BT" with a 3/4" brass disc stamped "RLS 1808" nailed low to face, bears S.9°40'E., 35.5 ft.