

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 260540

PRIMARY CORNER DESCRIPTION CE 1/16 Sec 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Marvin C. Ramsey - 3/1960 - C.S. File 51/86  
-----  
Set an iron pipe 3 ft. long 1" in dia., 28" in the ground  
mkd. RS404, from which  
A D.Fir 18" in dia., N.46°E., 19 lks. Mkd: CE 1-16 S8  
RS404 BT.  
A D.Fir 28" in dia., N.26°W., 60 lks. Mkd: CE 1-16 S8  
RS404 BT.

Ken Hoffine - For: Lone Rock Management Co. - 5/2016 - M172-7  
-----  
Set - 5/8" X40' iron rod with 2½" aluminum cap marked LONE  
ROCK TIMBER CE 1/16 S8 2016 PLS 2291  
14" D.Fir bears N.8¼°E., 9.3 ft. We scribe CE1/16 S8 BT  
and tag tree  
12" D.Fir bears S.11½°W., 39.0 ft we scribe CE 1/16 S8  
BT and tag tree  
Found Ramsey BT stumps with iron pipe pushed out of  
position. We reset corner at proportionate distance.  
Corner lies at north edge of three way road  
junction.  
We set corner 0.1 feet below the road surface and put a metal  
U - Post approx. 5.0 feet north of corner

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff  
Lorsung- 8/17/2023 - C.S. File 67/56-56  
-----  
Found - 5/8" I.Rod 8" below road surface.  
Burned-dead 14" D.Fir N.8¼°E., 9.3 ft. partly healed  
single blaze partial scribe visible, add 3½" mag  
nail, right side center.  
Metal U post N. 5°W., 5.0 ft.  
New - 5/8"x30" I.Rod with DCS0 yellow plastic cap N.75°W.,  
17.8 ft., up 6".  
Note - Area burnt 9/2020  
Compass decl. 14½°E.  
Mon on graded flat ridge at 3 way road intersection.  
Oregon Coordinate Reference System  
Cottage Grove - Canyonville Zone  
N 177869.752 E 264388.945