

PRIMARY CORNER DESCRIPTION Center ¼ Cor. Sec. 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Ronald Quimby, BHW Engineering - For: Watson Talcott
February 1981 - RM 3-45

Set - 5/8" x 30 Iron rod.
BTs - 40" D.Fir bears S.21°E., 66.0 ft. scribed "C ¼
S29 BT"
14" Oak bears N.79°E., 30.0 ft. mkd. "C ¼ S29 BT".

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause -
2/6/2008 - C.S. File 67/25-13

Found - 5/8" dia., iron rod, no cap, flush w/surface of
ground.
40" now 50" dia., D.fir, has triple top, fully
healed double blaze, bears S.15½°E., 66.0 ft.
(Rec. S.21°E., 66.0 ft.)
14" now 15" dia., W.Oak, fully healed double blaze,
bears N.89½°E., 30.0 ft (Rec. N.79°E., 30.0 ft)
Note - Report made to correct bearings to trees.
Corner lies approx. 15 ft. Southerly of centerline
of drive way at 2120 and 27 ft. east of
centerline of Little River Rd.
Compass decl. 16¼°E.