



PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike  
- 10/30/2007 & 11/5/2007 - C.S. File 67/24-42  
-----  
Found - 2½" dia., brass cap on a 2" O.D. iron pipe, properly  
marked, projects 9" above ground.  
16" now 20" dia., x 2 ft tall rotted fir stump, lies  
in remnants of old E-W fence scribing "SR3W"  
visible on rotted blaze bears N.39°E., 5.3 ft.  
(agrees w/rec) 1924 BT  
No sign of any other accessories found.  
New - 20" dia., I.Cedar, double blaze & scribed "T26S R3W  
S8 CS BT" bears S.86¼°W., 76.9 ft.  
27" dia., W.Oak double blazed & scribed "T26S R3W S8  
CS BT" bears N.27¾°W., 137.7 ft.  
Double trunk pear, westerly trunk is 9" dia., & is  
scribed "X" on high blaze & "CS BT" on low blaze,  
bears N.51°E., 31.8 ft.  
9" dia., W.Oak double blazed & scribed "T26S R3W S9  
CS BT" bears S.75½°E., 26.6 ft.  
Note - Corner lies approx. 18 ft East of dirt Rd.  
Dilapidated fence runs East out of corner.  
Compass decl. 16¼°E.

Adam DeGroot - For: Dollens & Strader - Dec. 2020 - M178-27  
-----  
Found - A 2" iron post by Mensch in 1924 per USGLO Survey of  
section 9, firmly set & projecting 12" above the  
ground with a 2½" brass cap properly mkd per the  
record, with accessories per the 2007 DCSO corner  
renewal c.s. file 67/24-42. This corner was not  
burned in the fire