

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 360320

PRIMARY CORNER DESCRIPTION SE 1/16 Sec. 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Bureau of Land Management subdivision of Section by White; Beck and Reynolds, Under Group #'s 242; 491 and 527. Survey June 1962-Aug. 1963 (DCSO records, Volume 32 Pages 13400-1)

Point for the SE1/16 sec. cor. of sec. 21, at the intersection with the E & W center line of SE ¼
Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked: SE 1/16 S 21
1963

from which
A Cedar, 17" dia. bears N.15°E., 49 lks. mkd: 1/16 S21 BT.
A Cedar, 20" dia. bears S.82°W., 42 lks. mkd: 1/16 S21 BT.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 1/8/2001 - C.S. File 66/19-3

Found - 1963 BLM brass/iron pipe, protrudes 1" out of ground. Properly marked.
Corner is NW 3 ft. of a 4-way fence corner.
20" now 30" dia., I.Cedar with a fully healed single blaze, bears S.82°W., 27.7 ft. 1963
17" dia., Cedar now root hole N.15°E., 32.3 ft. 1963
New - 13" dia., Maple double blazed & scribed "SE 1/16 S21 CS BT" bears N.41½°W., 28.8 ft.
9" dia., D.Fir double blazed & scribed "SE 1/16 S21 CS BT" bears N.20°E., 11.2 ft.
Compass decl. 17 3/4°E