

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Samuel C. Flint, Under Contract #454, dated June 19, 1882 (DCSO records, Vol. 10 Page 4390)

Set fir post, 3 ft. long, 3" sq., firmly in the ground for 1/4 sec. cor. marked 1/4 S on N and S faces, from which
A Fir 22" dia., bears N.74°E., 6 lks. dist.
A Chinquapin, 12" dia., bears N.52°W., 88 lks. dist.

Weyerhaeuser Timber Company & Youngs Bay Lumber, by Lester E. Calder; Glen McChesney; Tom Shrum; Don Wright April 1960 C.S. File 51/87-2 (1953? c.s. 53/115-10)

The joint survey of 1950-51 found no evidence of the original corner. The area has been covered by an old burn. 1950-51 survey set 3" sq. Yew post for corner by single proportion method. Referenced by Curtis Price (Plates & "W" nails only).
32" Fir N.22°W., 29.9 ft.
48" I.Cedar N.80°E., 36.1 ft.

Harley E. Case and John Wilson, for Weyerhaeuser Company May 1966, C.S. File 55/19-1

Found - No trace of GLO 1882 survey corner.
22" Fir N.74°E., 6 lks. - No trace
12" chinquapin N.52°W., 88 lks. - No trace.
Set 1" Monel Pipe for corner by single proportionate method. Referenced by Glenn McChesney (Plates & "W" nails only)
30" Fir, N.34°W., 25.4'
44" I.Cedar, N.84°E., 33.7'
NOTE: This supercedes the 1/4 corner set by Curtis Price for Weyerhaeuser Co. in 1950-51 survey of section 24, using staff compass and chain.

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - April 1, 2011 - C.S. File 67/33-25

Found - 1" ID monel pipe is firmly set and protrudes 4" above ground. 1965
We do not find the 1960 monument.
Remains of 2 BTs orig. mkd in 1960 & re-described in 1965
A 48" I.Cedar now 44" dia., 3 1/2 ft. tall, backless and rotted I.Cedar stump with a "W" nail on its face (no other markings fd) bears N.84°E., 35.7 ft. to center of root crown (CRC) (rec. N.84°E., 33.2 ft. (This distance is to "W" nail)) 1965 continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias	Description
Alias	Description
Alias	Description
Alias	Description

New - A 30" fir now a 36" dia., 2 ft. tall backless and rotted fir stump with no "W" nail in possible face; bears N.34°W., 27.2 ft. to CRC (Rec. N.34°W., 25.4 ft (this dist is to face of stump))

A 5" DBH D.Fir scribed "¼ S13 CS" "BT" on a double blaze; bears N.48°E., 13.8 ft.

A 17" DBH hemlock (intergrown at the NE edge of its base with a 12" DBH D.Fir) scribed "¼ S24 CS" "BT" on a double blaze. The CRC of the combined two trees bears S.46°E., 4.3 ft.)

A 6" DBH D.Fir scribed "¼ S24 CS" "BT" on a double blaze; bears S.55°W., 13.3 ft.

A 17" DBH D.Fir scribed "¼ S13 CS" "BT" on a double blaze; bears N.13°W., 18.4 ft.

Note - Monument is on very gentle north slope in older mixed fir and hemlock reprod forest; approx 75 ft north from a graveled forest road.
15¾°E decl.

Fd as per 2011 DCS rehab. by D. Edwards, 10/2012 - M164-32

Dependent resurvey by Jeffrey O Covington, cadastral Surveyor under Group 2953, Surveyed Sept/Oct 2019 (DCSO Records Vol. 59 Pages 23986-23988 and Plat maps T26-3 2021-1 thru 2021-3)

The ¼ sec cor of secs 13 & 24, reestablished by proportionate measurement by Wilson, Washington State PE No 2526, in 1965; and perpetuated by Smith, in 2011. There is no remaining evidence of the original cor., therefore this point is accepted as a careful and faithful reestablishment of the cor monumented with an aluminum pipe, 1¼" dia., firmly set, projecting 6" above ground, from which the remains of the BTs mkd. by Calder PE No 2149, in 1952, reported by Wilson

A decayed fir stump, 36" dia., bears N.34½°W., 27 0 ft., no marks visible.

A decayed cedar stump, 44" dia., bears N.82¾°E., 35.3 ft., no marks visible.

and the bearing trees mkd. by Smith

A fir, 6" dia. bears N.47½°E , 14.1 ft., with a healed blaze.

A hemlock, 17" dia., bears S.43°E ,.4.9 ft., with scribe marks ¼ S14 CS BT visible on partially healed blaze.

A fir, 9" dia bears S.56¾°W., 13.3 ft., with a healed blaze.

A fir, 20" dia., bears N.11¼°W., 18.9 ft., with a healed blaze.

Continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

At the corner point
Set a stainless steel post, 28" long, 2½" dia , 26" in the ground, directly over the aluminum pipe, with brass cap mkd.

T26S R3W

¼ $\frac{S13}{S24}$

2019

From this cor., a point established as the ¼ sec. cor. of secs. 13 and 24, by Calder, subsequently rejected by Wilson, and was not utilized for control in this survey, bears S.16°23'53"W., 1.89 ft; as determined at Calder's record bearings and distances from the remains of the bearing trees reported by Wilson.

From the corner, N.89°22'50"W.;

765 ft. dist. spur, slopes N.40°E.

2035 ft. dist., creek, 2 ft. wide, course N.20°W.

2440 ft. dist, creek, 2 ft. wide, course N.30°E.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 5/25/2021 (Filed 11/22/2021) - C.S. File 67/51-8

2019 BLM survey now filed see above renewal (3/15/2022)

Found - A 3¾" dia., BLM brass cap on a 2" I.D. iron pipe fd projecting 1" above ground. Monument from pending BLM resurvey not yet recorded at DCS0. MKD:

T26S R3W

¼ $\frac{S13}{S24}$

2019

From the 2011 DCS0 renewal the four new BTs are all now fire killed and partially burned -

An 8" dia., dead D.Fir with fully healed double blaze blocked by fallen material - We do not check B&D

A 19" dia., dead hemlock with a burned partially healed double blaze showing some illegible scribing; bears S.46°E., 5.1 ft. (to right side center nail, record 4.3 ft.)

A 9" dia., dead D.Fir with a fully healed double blaze; bears S.59°W., 13.8 ft. (record S.55°W., 13.3 ft.) new to right side-center nail.

A 20" dia., dead D.Fir with a fully healed double blaze; bears N.13°W., 18.9 ft. (to right side center nail, rec. 18.4 ft.)

New - A fire killed 9" dia., D.Fir, not blazed or scribed but a 4" spike nail is driven in tree's right side center, this tree bears N.49°E., 19.9 ft.

Note - Corner is approx. 75 ft North of graveled forest rd. Area badly burned Sept. 2020 Cont.

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Compass decl. $14\frac{1}{2}^{\circ}\text{E.}$

Lat: $43^{\circ}18'01.14''$

Long: $123^{\circ}00'01.63''\text{ W}$