

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 36; & S31 of T26-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

6" now 6" dia., 3 ft. high cedar staub with scribing visible "S36 BT" bears S.83°W., 5.3 ft. (Agrees with rec.) 1913 GLO
5" now 16" dia., D.Fir with a fully healed blaze, bears S.47°E., 24.5 ft. (Agrees with rec.) 1966 DCSO
12" now 22" dia., Cedar with a fully healed blaze, bears N.9°W., 29.6 ft. (Agrees with rec.) 1966 DCSO
New BTs- 9" dia., D.Fir double blazed & scribed "¼ S36 CS BT" bears S.45°W., 2.0 ft
11" dia. D.Fir double blazed & scribed "¼ S31 CS BT" bears N.57°E., 9.5 ft

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22920)

The ¼ sec. cor. of secs. 31 and 36, perpetuated by the Douglas County Surveyor's Office in 1966, further perpetuated by Smith, Deputy County Surveyor, in 1998, monumented with an iron post, 1¼" dia., firmly set, projecting 13" above ground, with brass cap (properly) mkd. from which the remains of an original bearing tree
A roothole bears N.50°E., 15.8 ft., alongside of which is an uprooted, decayed, sawed fir stump, 30" dia., with no marks visible on a decayed, partially healed blaze. and the BTs mkd. by the Douglas County Surveyor's Office
A fir, 19" dia., bears S.47½°E., 24.7 ft., with a healed double blaze.
A cedar, 23" dia., bears N.9¾°W., 29.5 ft., with a healed double blaze.
and the bearing trees mkd. by Smith
A fir, 13" dia., bears N.58°E., 9.8 ft., with a healed double blaze.
A fir, 11" dia., bears S.34½°W., 2.0 ft., with a healed double blaze.
Corner is located 230 ft. N. of a draw, drains, S.50°E.