

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 039080

PRIMARY CORNER DESCRIPTION NE Int. L Cor Tyrell DCI #39

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #28 dated April, 1854

To cor at angle in east boundary of C 39, Set post in prairie, deposited stone 8 x 4. Raised mound with trench as per instructions.

James W. Byron, Deputy Co. Surveyor, September 1954
C.S. file 46/74 and R.M. 1-14

Found no evidence of old corner. Corner set by proportional measurement. Set an I.P. with brass cap mkd. Cl 39 N.E. Int. L cor. T26S R5W County Surveyors office 1954.

Blazed and scribed:

14" W.Oak S.26°18'E., 747.7 ft mkd. N.E. Int L Cl 39 CS BT
6" W.Oak S.87°48'E., 713.3 ft. mkd. Int. L Cl 39 CS BT

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch
- April 11, 2013 - C.S. File 67/38-22

Found - No evidence of orig. monument.

A 2½" dia., brass cap on a 1" I.D. dia., iron pipe which is bent and leaning approx. 1.3 ft. NW'ly from its plumb position. Monument protrudes approx. 14" above a rough, low 2 ft dia., mound of stone. 1954

Accessories are measured from fd monuments plumb position. (All measured bearings are true and are based on record, DCSO map RM 1-14, between NE Int. L and NE Ext. L of DLC 39)

A 6" W.Oak, now a 15" dia., W.Oak with blazes no longer visible; bears S.87¾°E., 713.3 ft. (as per rec) 1954

A 14" W.Oak now a 31" dia., W.Oak with a fully healed double blaze; bears S.26¼°E., 747.7 ft. (as per rec) 1954

New - The plumb position of the 1954 BC is referenced out, the monument is removed and in its place is set a new BC on a 1" I.D. x 30" long iron pipe plumbly positioned approx. 6" below ground, the low stone mound is replaced over the monument position. BC marked:

DOUGLAS COUNTY SURVEYORS

T26S R5W
NE INT L
DLC | _____
39

2013

continued next page

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 039080

PRIMARY CORNER DESCRIPTION NE Int. I Cor Tyrell DCI #39

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A $\frac{5}{8}$ " dia., iron rod, firmly and plumbly set protruding 4" above ground (1 ft. South of an E-W fence line and $7\frac{1}{2}$ ft. East of corner of fences running SSW & East) bears $S.81\frac{1}{2}^{\circ}W.$, 228.78 ft,
A $2\frac{7}{8}$ " dia., DCSO brass cap stamped "NU 15 1972" set flush in top of an 8" dia., concrete filled, concrete bell tile, firmly and plumbly set protruding 4" above ground ($2\frac{1}{2}$ ft. West of a NNE running fence); bears $N.78\frac{1}{2}^{\circ}W.$, 230.42 ft.
A $\frac{5}{8}$ " dia., iron rod, firmly and plumbly set protruding 10" above ground (at corner of fences running North & East); bears $N.27\frac{3}{4}^{\circ}W.$, 370.63 ft
Note - Monument is in flat open pasture 20 ft. north of gravel driveway for #724 North Bank Rd. Monument is approx. 250 ft. East from centerline of North Bank Rd.
Compass decl. $15\frac{1}{2}^{\circ}E.$