

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; and 31 of T25-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>Original - Elder &amp; Gile, Contract #31 dated April, 1853 ----- Set qr. sec. post, from which: drove chained stake and raised mound with trench.</p>
<p>Francis L. Ingram, Deputy Co. Surveyor - John M. Powell January 21, 1972 - C.S. File 56/10 and M 44-48 ----- This corner set from resurvey of township line Set - Brass cap at 1/4 cor. mkd. County Surveyors Office 1972 T 25 S R 5 W 1/4 S 31 S 6 T 26 S  Bearing Objects: 5/8" Iron rod S.43°W., 17.0 ft. 5/8" Iron rod S.31°E., 14.4 ft. (SE I.R. set at fence cor. Fences running E-W-S) This cor. lies 12.0 ft. north of East-West fence line.</p>
<p>Found brass cap, April, 1988, D. Bentz - M 106-4</p>
<p>Fd BC by Mark Heimburger, 9/2006 - M146-47 Grid N: 624,504.223 Grid E: 4,166,992.268 Latitude 43°20'42.706" Longitude -123°20'10.330" Convergence -1°56'25.37"</p>
<p>Andrew Ausland, ODOT - June 2012 - M163-64 A-C ----- Fd. 2 1/2" dia., brass disk (properly) stamped 0.1 ft. above surface, good condition.</p>
<p>Fd. DCSO BC by M Heimburger, 3/2014 - M168-9</p>
<p> </p>