

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor for Secs. 11 and 14

Alias 039020 Description NW Cor. DIC #39  
Alias 855400 Description M.C. Right Bank Umpqua River  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
-----

Set 1/4 Sec. post (also for Meander post), from which  
A W.Oak 10" dia. bears N.21 1/4°W., 16 lks.  
An alder 13" dia. bears S.70°W., 87 lks.

James W. Byron, Deputy Co. Surveyor - September, 1954  
C.S. File 46/74 (pgs 34-35) and R.M. 1-14  
-----

BTs of original survey not found. Point for corner located by  
proportional distance between Meander corner & the NE corner  
of section 14.

Set - An iron pipe with brass cap at corner mkd. County  
Surveyor's office, 1/4 Corner M.C. 1954 Sec. 11  
Sec. 14

Blazed & scribed:

30" B.Oak N.7°43'W., 201.0 ft. mkd. 1/4 S11 MC CS BT.  
14" B.Oak S.43°10'W., 67.5 ft. mkd. 1/4 S14 MC CS BT.  
11" W.Oak S.79°15'E., 332.3 ft. mkd. 1/4 S14 MC CS BT.

Milo E. Godfrey, Deputy - Wm. Stoffel; Mike Stone January,  
1964 - C.S. File 49/125-29  
-----

Found - Brass cap set in 1954, in place but bent over.  
11" W.Oak S.79 1/4°E., 332.3 ft. alive & in good  
condition, scars plain.  
30" B.Oak N.7 3/4°W., 201.0 ft. still standing, but  
most of S. face & blazes burned away, some  
scribing still visible on edge of scars.  
Burned remains of Oak stump S.43°W., 67.5 ft.  
Drove steel fence post alongside brass cap.

New BTs - 17" B.Oak S.27 1/2°W., 106.2 ft. mkd. 1/4 S14 CS BT.  
34" B.Oak N.10°W., 219.0 ft. mkd. 1/4 S11 CS BT.

Note: Corner is in cultivated field approx. 50 ft. E. of  
River bank.

Corner fd. Feb. 1985, G. Baughman, M 98-28  
Corner fd., No BT's - Jan 1994 - D. Bentz, M118-27

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -  
Stephen J. Flause - 2/26/2001 - C.S. File 66/19-45  
-----

Found - 1954 DCSO brass cap iron pipe badly bent protrudes  
8" out of ground.

11" now 15" dia., W.Oak with a fully healed double  
blaze bears S.79 1/4°E., 332.3 ft. 1954

No other BTs found. continued next page

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor for Secs. 11 and 14

Alias 039020 Description NW Cor DLC #39  
Alias 855400 Description M.C. Right Bank Umpqua River  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

New - 19" dia., W.Oak double blazed & scribed "¼ S11 CS  
BT" bears N.54½°E., 455.2 ft.  
5/8" iron rod per 1985 M99-55 bears S.88¼°E., 637.3  
ft. (Westerly R/W pin) on DLC Line.  
27" dia., W.Oak double blazed & scribed "¼ S11 CS  
BT" bears N.4 3/4°E., 325.6 ft.  
1954 BC/IP straightened and returned to plumb  
position protrudes 2" above ground.  
Compass decl. 17 3/4°E.  
See last Pg for pictures.

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor for Secs 11 and 14

Alias 039020 Description NW Cor DIC #39

Alias 855400 Description M.C Right Bank Umpqua River

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

