

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 360420

PRIMARY CORNER DESCRIPTION SE 1/16 Cor. for Section 16

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas County Surveyors Office - P. Earle; F. Silagy  
October 16, 1979 - C.S. File 60/34-20

-----  
Found - 1" Iron pipe with brass cap set 16" out of ground  
stamped: T26S R6W SE 1/16 + S16 1968 LS 536"  
as recorded by G. Baughman, Co. Surveyors  
Records, M 35 - 61.

A 20" W.Oak now a 20" dia. Oak stump 24" high bears  
S.28°W., 39.4 ft. (Rec. S.26°45'W., 39.4 ft.)  
Lower blaze remains partially healed, "BT"  
scribing visible.

A 16" now 22" Madrone bears N.87°E., 40.0 ft. (Rec.  
S.86°W., 40.0 ft.) with a partially healed  
double blaze, scribing SE 1/16 BT visible.  
The blaze on the Madrone faces the present  
location of the BC. The cap was found firmly  
set in ground. For these reasons along with the  
agreement of the other bearing & distances, we  
determine this bearing to the madrone was re-  
corded in reverse.

New BT - A 6" W.Oak bears S.27°E., 27.2 ft. scribed "SE 1/16  
S16 CS BT" on a double blaze.

Corner lies 50 ft. North of dirt road course S-W.