

PRIMARY CORNER DESCRIPTION Sec Cor for 27, 28, 33 & 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
-----

Set post cor. to secs. 27, 28, 33 & 34, from which  
A W.Oak 12" dia. bears S.67¼°E., 264 lks.  
A W.Oak 15" dia. bears S.48½°W., 327 lks.  
A Y.Oak 16" dia. bears N.87¼°W., 406 lks.  
A Y.Oak 28" dia. bears N.21½°E., 78 lks.

J. W. Cole, Deputy Co. Surveyor - May 1921 - M 1-69  
F.B. 51 Pg. 4  
-----

I renewed this corner from one orig. BT, S.67°15'E., 174.2 ft.  
(Note, this corner is set wrong. It is 77 ft. on the ground,  
calls for 264 lks.) which is alive & standing & bearing scribe  
marks, also by tie to Meander Cor. which I located from one of  
the bearing trees. I set an Oak post for sec. cor., also  
erected a mound of rock. Marked new trees as follows:

A W.Oak 10" dia. N.50°W., 47 ft.  
A W.Oak 10" dia. S.38°W., 54 ft.

James W. Byron, Deputy - Dale McFarland; J.Powell - August 11,  
1961 - C.S. File 52/87-4  
-----

Found - Mound of stone at corner & 10" now 16" W.Oak  
N.50°W., 47.0 ft. We open & find good  
scribing "2".

Also find SW BT as recorded by Cole.

Set - Brass cap at cor. mkd. County Surveyors Office, 1961

S28|S27 T26S R6W  
S33|S34

New BTs - Rescribe, now 16" W.Oak N.50°W., 47.0 ft. T26S R6W  
S28 CS BT.

10" W.Oak bears S.50½°W., 67.3 ft. scribed S33 T26S  
R6W CS BT.

11" W.Oak bears S.45°E., 101.3 ft. scribed S34 T26S  
R6W CS BT.

7" B.Oak double, bears N.47°E., 68.5 ft. scribed  
S27 CS BT.

Found OK, M.E.G., June 1964, C.S. 52/87-36  
Found OK, D. Stringer, July 1986 - M 102-28  
continued next page

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Stephen Flause; R.W. Smith;  
December 5, 1986 - C.S. 62/38-4

-----  
Found - 1961 DCSO 2 3/8" brass cap properly mkd. on a 1"  
I.Pipe firmly set & protrudes 1" above ground.  
An orig. W.Oak 12" dia. now a 20" DBH W.Oak with a  
fully healed single blaze bears S.67¼°E., 175.5  
ft. (Rec. S.67¼°E., 174.2 ft. possible face  
measurement).

No other orig. BTs found.

A W.Oak 10" now a 14" DBH W.Oak (called 16" in 1961  
when rescribed) with a fully healed single  
blaze, bears N.50°W., 47.0 ft. (per record)

A W.Oak 10" now a 18" DBH W.Oak with a partially  
healed single blaze with no scribing visible,  
bears S.38°W., 54.0 ft. (per record)

A 10" W.Oak now a 14" DBH W.Oak with a fully healed  
double blaze bears S.50½°W., 67.3 ft.(per rec)

No other Byron trees found.

Tie to newly reset meander corner S.33 and S34 on North bank  
of North Umpqua River checked; bears South 97.0 ft. dist. as  
per record to position as determined from bearing trees found.

New BT - A W.Oak 13" DBH scribed "T26S R6W S34 CS BT" on a  
double blaze bears S.30°E., 81.5 ft.

Monument is approx. 105 ft. North from North Bank of North  
Umpqua River & approx. 35 ft. west from a north-south  
fenceline. See DCSO geodetic control book for coordinates.

Found Jan. 1991 -M.L.P. 1991-0006

Found O.K. - June 6, 1993 by William, Ruppert - 1993-0039

Found O.K. - Feb. 13, 1996 by D. Bentz - Vol. 18 Pg. 59 A-C

Fd. Ok by K. DeGroot, April 2009, M159-17