

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 700240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 25; & 30 of T26-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set $\frac{1}{4}$ Sec. post, from which
 A W.Oak 30" dia. bears S.64 $\frac{1}{4}$ °E., 1123 lks.
 A Y.Oak 30" dia. bears N.75°W., 1003 lks.

A. Boyer, D.C.S. Dec. 22, 1944 - (No source reference found,
see "old" cor. renewal Vol. 1 Pg. 69)

Set a 6 x 9 x 12" sandstone, from original BT., 10" ground.
BT is a W.Oak in good condition. Used U.S. field notes which
are a 30" (now about 36") W.Oak bears S.64°15'E., 741.2 ft.
The other BT gone. Marked stone with a $\frac{1}{4}$ S. on top, set an
Iron rod alongside stone.

J.W. Byron, Deputy Co. Surveyor - R. Irving; John Fee
For: Darley Ware - May 24, 1954 - C.S. 46/6, M 8-12

Found 4" x 4" x 5 ft. Cedar post. Also a 6" x 6" square
sandstone rock, 6" under surface mkd $\frac{1}{4}$ S. Also found 5/8" Rod.
Blazed and Scribed:
 10" W.Oak S.60 $\frac{1}{2}$ °E., 483.5 ft. mkd. $\frac{1}{4}$ S30 CS BT.

FD, not renewed, 7/11/78, L. Monrean DCSO, C.S. file 60/11-27

Douglas Co. Surveyors Office - Stephen Flauser; Terrie Plouff
June 4, 1981 - C.S. File 61/24-31

Found - A 3/4" dia. I.Rod protrudes 2" above ground & is
 firmly set.
 A stone measuring approx. 6"x7" on its uppermost
 surface & thereon mkd. $\frac{1}{4}$ S, lies 1" below the
 surface of the ground & lies on the NE edge
 of the above mentioned I.R.
 An orig. W.Oak 30" dia. now 41" (DBH) bears
 S.64 $\frac{1}{4}$ °E., 741.2 ft. (per rec.) & has a healed
 blaze with no scribing visible.
 No evidence of orig. Y.Oak found.

(Cont next page)

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 700240

PRIMARY CORNER DESCRIPTION 1/4 Cor for Sec. 25; & 30 of T26-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 10" W.Oak now an 18" DBH W.Oak bears S.66½°E.,
483.5 ft. (per rec) & has a healed double blaze
with no scribing visible.
Monuments found are accepted.
New Accessories: (Two property corner monuments in the Subd.
"Saddle Butte Estates, 1st Addn.")
The NW cor. of Lot 15, which is a 5/8" x 30" I. rod
firmly set & protruding 4" from ground, bears
N.13¼°E., 423.7 ft.
The SW cor. of Lot 16, which is a 5/8" I.R. with an alum.
cap mkd. "SHANER ENGINEERING", firmly set &
protruding 3" from ground near the South edge of a
6" square 6 ft. tall cedar post bears N.56¾°E.,
314.1 ft.

Found OK 5/31/84 - DCSO - C.S. file 62/18-4
Found Rod & Stone, B. Shaner, June, 1990 - M 112-1
