

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and new bearing trees
A Fir 12" dia., bears N.88½°E., 41 lks., mkd. ¼ S10 BT.
A Fir 8" dia., bears N.11°W., 215½ lks., mkd. ¼ S9 BT.
Corner falls on E. bank of creek, 5 lks. wide, course N.5°E.

T.E. Shrum, for: Champion International - Sept. 17, 1981
M 89-29

Found - 3½" 1963 brass cap.
8" D.Fir bears N.11°W., 142.2 ft.
New BT - 6" D.Fir bears N.65°E., 6.7 ft.

Fd. OK, H. Pieske, May, 1988, M 106-25

BLM Dependent resurvey by Timothy J Moore, Cadastral Surveyor & Robert H Browning, Surveying Tech. under Group #2075, surveyed April/June 2005 (DCSO rec. Vol. 56 pg(s) 22080-1)

The ¼ sec. cor. of secs. 9 & 10, monumented with an iron post, 2½" dia., firmly set, projecting 12" above the ground, with brass cap (properly) mkd.
from which the remains of a bearing tree mkd. by Beck
A roothole, bears N.85½°W., 22.4 ft., alongside of which is the displaced sawed cedar stump, 17" dia., no marks visible.
and the remaining bearing tree mkd. by Roseberry and Garrison
A fir, 19" dia., bears N.11°W., 142.2 ft., with a healed blaze.
and a BT mkd. by Shrum, in 1981
A fir, 17" dia., bears N.62°E., 6.6 ft., with a healed blaze.
Corner is also located in a 5 strand barbed wire fence, extending north and south; also located east, 7.0 ft. of a creek, 1½ ft. wide, course N. 15° W.
