

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original, Dennis Hathorn, under Contract #57 dated April 12, 1855 (DCSO records, Volume 11 Page 4607)

-----  
Set ¼ sec. post, from which  
    A W.Oak 20" dia., bears N.40°E., 22 lks. dist.  
    A B.Oak 24" dia., bears N.35°W., 161 lks. dist.

Doug. County Surveyors Office - James W. Byron, Deputy  
Milo Godfrey; Clete Putnam - May 1960 - C.S. File 49/129-6

-----  
Found - Orig. 24" now 30" Oak stump N.35°W., 106.3 ft. most  
          of center rotted but I do find small section  
          of old face that shows reverse scribing "T".  
          ¾" Iron pipe at corner.  
          No trace of original NE BT found.  
Set Brass cap alongside ¾" Iron pipe, marked: ¼ S10|S11 T26S  
R7W, County Surveyor's Office, 1960.  
New BTs - 7" W.Oak S.46°E., 13.5 ft. scribed ¼ S11 Cs BT.  
          18" W.Oak N.37°W., 31.0 ft. scribed ¼ S10 CS BT.

Doug. County Surveyors Office - Randall Smith, Deputy -  
Stephen Flause; Terrie Franssen - Feb. 13, 1991 - C.S. File  
64/13-4

-----  
Found - 1960 2½" dia. DCSO brass cap on a 1½" O.D. iron  
          pipe protruding 10" above ground.  
          ¾" I.D. Iron pipe protruding 12" above ground is  
          along northwest edge of DCSO BC/IP.  
          7" now 10" dia. W.Oak with a fully healed double  
          blaze, bears S.46°E., 13.5 ft. (agrees w/rec)  
          18" now 26" dia. W.Oak with a fully healed double  
          blaze bears N.39°W., 31.0 ft. (Rec. N.37°W.)  
          24" dia. Oak now stump hole, bears N.35°W., 106.3  
          ft. Original BT.  
New BTs - 19" dia. W.Oak double blazed & scribed ¼ S11 CS BT  
          bears N.87°E., 22.8 ft.  
          21" dia. W.Oak double blazed & scribed ¼ S10 CS BT  
          bears N.78°W., 137.9 ft.  
Corner is approx. 600 ft. South of a paved BLM road.

Fd as per rec. 1/2022 - D. Edwards - M180-39  
Fd. as per record 11/2023 by D. Edwards 2023-0037