

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION WC 1/4 Cor. Secs. 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Contract #57 dated April 12, 1855
(DCSO records, Volume 11 Page 4596)

Set ¼ sec. post, from which
 A W.Oak 12" dia., bears S.78°E., 170 lks. dist.
 A B.Oak 12" dia., bears N.12°W., 136 lks. dist.

Doug. County Surveyors Office - James W. Byron, Deputy
Milo Godfrey; Clete Putnam - Aug. 26, 1959 - C.S. 49/129-7

Found - Orig. 12" now 24" W.Oak S.78°E., ~~12.2~~ 112.2* ft.,
 previously, shows good scribing "¼ S".
 No trace of original NW BT.

Milo Godfrey states that he was with Richardson about 1949
and they opened the SE BT., also drove a rod at corner which
we do not find. The scribed new BTs which we record at this
time. Richardson's work was not recorded.

Set ¾" Iron rod at corner.
15" W.Oak N.56°E., 84.8 ft. shows good scars. I do not open.
16" W.Oak N.52°W., 43.2 ft., I open & find good scribing.
*upon looking at the original record, it reads 112.2, the
first "1" was written on a grid line. DCSO JC 4/18/2023

Doug. County Surveyors Office - John M. Powell; W. Penley
July 12, 1971 - C.S. File 54/23-17

Found - ¾" I.Rod 6" underground at ¼ cor.
 15" W.Oak N.56°E., 84.8 ft., now stump.
 16" W.Oak N.48°W., (Rec. N.52°W) 43.2 ft., shows
 good scar.

As this corner will fall in new road work, I SET WIT. COR.
mkd. as follows: County Surveyors T 26 S R 7 W
 Office, 1971 ¼

 S35 | S36
 W.C. 60 ft. S. to
New BTs - 16" W.Oak, East 5.0 ft. scribed WC ¼ S36 CS BT.
 5/8" I.Rod, S.48°W., 46.0 ft. This rod in old R/W
 fence line.

Found OK, V.R.T. July, 1973, C.S. File 56/34-16

Doug. County Surveyors Office - Gary L. Langlitz, Deputy
John E. Nordling, Jan. 27, 1975 - C.S. File 57/17-22

Found - 1" I.Pipe, firmly set with brass cap attached for
 W.C. for the ¼ corner.

Continued next page

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION WC 1/4 Cor Secs 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 5/8" Iron rod bears S.48°W., 46.0 ft.
16" W.Oak, now a stump, bears East 5.0 ft. with
scribing "WC 1/4 S36 CS BT" visible.
We note a new bearing object as follows:
A 5/8" Iron rod at Engineers Station 222+10 POC 35'
left of the centerline of Co. Rd. #53 (Elgarose
Rd.) (East side of road), bears S.3°E., 275.7
ft.
We note the two bearing trees are still in existence for the
true 1/4 corner:
Orig. SE BT with scribing "1/4S" visible.
NW BT reported in 1959 by Byron and Godfrey.
We do not search for any evidence of record monuments at the
true 1/4 corner.
*The distance to the orig. SE bearing tree as shown by Byron
and Godfrey is erroneous, it should be 112.2 ft., not 12.2 ft
Compass declination setting: 20° east.*upon looking at the
original record, C.S. 49/129-7, it reads 112.2, the first "1"
was written on a grid line. DCSO JC 4/18/2023

Romanso E. Ware: For Leonard Langley - February 1977, M 63-29

Found - Witness corner 60 ft. North.
Set - 5/8" Iron Rod at 1/4 corner.

Found OK, H. Stockhoff, March 1992, Partition 1992-0025

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff
Lorsung- 3/30/2023 - C.S. File 67/55-68

Found - 1971 DCSO brass cap (WC) (60' north of true corner
- BC properly mkd)
5/8" I.Rod S.51°W., 45.6 ft. (rec. S.48°W., 46.0
ft), up 3"
5/8" I.rod Engineers station 222+10 P.O.C. 35' left
of centerline S.3°E., 275.7 ft (not checked)
NW BT reported in 1959 by Bryon & Godfrey (see 1975
corner report)
New - 1" DCSO copper disk stamped "SURVEY MARK" S.12½°E.,
31.0 ft. Set flush in pavement over 3½" mag nail.
1" DCSO copper disk stamped "SURVEY MARK" S.12½°E.,
55.6 ft. Set flush in pavement over 3½" mag nail.
Note - Compass decl. 14½°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone to witness corner
N 157611.729 E 123429.832